



\*CS53L30 has 2 I2S output for 4 mic. However, CP2615 has only 1 I2S input. Thus, 4 mics are not available at the same time.



