

Power rails
VBAT 11.1 V from SW1: load 6.316 A typical, 22.616 A peak; source 35 A cont, 70 A peak; fuse 15 A
5V 5 V from U6: load 1.23 A typical, 5 A peak; source 5.5 A cont, 8 A peak
Fuses: F1 15 A (everything on VBAT), F2 2 A (branch regulator_5v). Branch fuses sit inline in the lead they protect.
Lever splices (star_ground, splice_vbat) are junctions of their nets.
Same net label or power symbol = same conductor. X = pin not connected.
Declared, no pins: MOTOR_DRIVER_1_CTRL_GND, MOTOR_DRIVER_2_CTRL_GND

Text to Robot generated from design.wiring

Title
four_wheel_robot: schematic

17 parts, 38 nets, 54 wires, 2 rails

Size: A1	Rev: 40dfadc1	Sheet 1 / 1
File: schematic.svg	KiCad symbol style	Id: 1/1