COLD CHAIN COMPLIANCE SYSTEM

Deviation Audit History Report

Field	Value
Deviation ID	3
Shipment ID	SHP-2026-000001
Original Decision	Fail
Current Status	Closed
Created At	31 Oct 2026, 11:33 AM IST
Last Updated	01 Nov 2026, 03:03 PM IST
Total Audit Events	8

Chronological Audit Events

Event #6 — Created

Timestamp	31 Oct 2026, 11:33 AM IST
Performed By	aditi
Previous Status	--
New Status	Open
Notes	Deviation opened from compliance report
Root Cause	--
Corrective Action	--
Action Owner	--
Due Date	--

Event #7 — Status Change

Timestamp	31 Oct 2026, 11:36 AM IST
Performed By	aditi
Previous Status	Open
New Status	Under Investigation

Notes	Temperature excursion detected. Investigating possible causes.
Root Cause	--
Corrective Action	--
Action Owner	--
Due Date	--

Event #8 — Status Change

Timestamp	31 Oct 2026, 11:38 AM IST
Performed By	aditi
Previous Status	Under Investigation
New Status	Corrective Action
Notes	Refrigeration issue identified
Root Cause	--
Corrective Action	Repair cooling equipment
Action Owner	Maintenance Team
Due Date	2026-11-08

Event #9 — Status Change

Timestamp	01 Nov 2026, 02:35 PM IST
Performed By	aditi
Previous Status	Corrective Action
New Status	Under Investigation
Notes	Test investigation initiated for shipment SHP-2026-000001. Compliance report indicates that no logger was assigned to the shipment. The issue requires review of logger assignment records and shipment monitoring procedures.
Root Cause	--
Corrective Action	--
Action Owner	--
Due Date	--

Event #10 — Status Change

Timestamp	01 Nov 2026, 02:39 PM IST

Performed By	aditi
Previous Status	Under Investigation
New Status	Corrective Action
Notes	Test investigation initiated for shipment SHP-2026-000001. Compliance report indicates that no logger was assigned to the shipment. The issue requires review of logger assignment records and shipment monitoring procedures.
Root Cause	Logger assignment was not completed before shipment dispatch.
Corrective Action	Introduce a mandatory pre-dispatch logger assignment check and verify logger calibration before shipment release.
Action Owner	Quality Assurance Team
Due Date	2026-11-01

Event #11 — Status Change

Timestamp	01 Nov 2026, 02:41 PM IST
Performed By	aditi
Previous Status	Corrective Action
New Status	Under Investigation
Notes	Demonstration closure: corrective action documented and reviewed for the synthetic logger-assignment deviation.
Root Cause	--
Corrective Action	--
Action Owner	--
Due Date	--

Event #12 — Status Change

Timestamp	01 Nov 2026, 03:02 PM IST
Performed By	siri
Previous Status	Under Investigation
New Status	Corrective Action
Notes	Test investigation initiated for shipment SHP-2026-000001. Compliance report indicates that no logger was assigned to the shipment. The issue requires review of logger assignment records and shipment monitoring procedures.
Root Cause	Logger assignment was not completed before shipment dispatch.

Corrective Action	Introduce a mandatory pre-dispatch logger assignment check and verify logger calibration before shipment release.
Action Owner	Quality Assurance Team
Due Date	2026-11-01

Event #13 — Status Change

Timestamp	01 Nov 2026, 03:03 PM IST
Performed By	siri
Previous Status	Corrective Action
New Status	Closed
Notes	Demonstration closure: corrective action documented and reviewed for the synthetic logger-assignment deviation.
Root Cause	Rogger assignment was not completed before shipment dispatch.
Corrective Action	--
Action Owner	--
Due Date	--

Generated from the append-only DeviationEvent audit history.