Cold Chain Compliance System

Deviation Investigation Report

Field	Value
Deviation ID	3
Shipment ID	SHP-2026-000001
Original Decision	Fail
Current Status	Closed
Root Cause	--
Corrective Action	--
Action Owner	--
Due Date	--
Created At	31 Oct 2026, 11:33 AM IST
Updated At	01 Nov 2026, 03:03 PM IST

Audit History

Created — 31 Oct 2026, 11:33 AM IST

Actor: aditi

Status: -- to Open

Notes: Deviation opened from compliance report

Status Change — 31 Oct 2026, 11:36 AM IST

Actor: aditi

Status: Open to Under Investigation

Notes: Temperature excursion detected. Investigating possible causes.

Status Change — 31 Oct 2026, 11:38 AM IST

Actor: aditi

Status: Under Investigation to Corrective Action

Notes: Refrigeration issue identified

Corrective Action: Repair cooling equipment

Owner: Maintenance Team

Due Date: 2026-11-08

Status Change — 01 Nov 2026, 02:35 PM IST

Actor: aditi

Status: Corrective Action to Under Investigation

Notes: Test investigation initiated for shipment SHP-2026-000001. Compliance report indicates that no logger was assigned to the shipment. The issue requires review of logger assignment records and shipment monitoring procedures.

Status Change — 01 Nov 2026, 02:39 PM IST

Actor: aditi

Status: Under Investigation to Corrective Action

Notes: Test investigation initiated for shipment SHP-2026-000001. Compliance report indicates that no logger was assigned to the shipment. The issue requires review of logger assignment records and shipment monitoring procedures.

Root Cause: Logger assignment was not completed before shipment dispatch.

Corrective Action: Introduce a mandatory pre-dispatch logger assignment check and verify logger calibration before shipment release.

Owner: Quality Assurance Team

Due Date: 2026-11-01

Status Change — 01 Nov 2026, 02:41 PM IST

Actor: aditi

Status: Corrective Action to Under Investigation

Notes: Demonstration closure: corrective action documented and reviewed for the synthetic logger-assignment deviation.

Status Change — 01 Nov 2026, 03:02 PM IST

Actor: siri

Status: Under Investigation to Corrective Action

Notes: Test investigation initiated for shipment SHP-2026-000001. Compliance report indicates that no logger was assigned to the shipment. The issue requires review of logger assignment records and shipment monitoring procedures.

Root Cause: Logger assignment was not completed before shipment dispatch.

Corrective Action: Introduce a mandatory pre-dispatch logger assignment check and verify logger calibration before shipment release.

Owner: Quality Assurance Team

Due Date: 2026-11-01

Status Change — 01 Nov 2026, 03:03 PM IST

Actor: siri

Status: Corrective Action to Closed

Notes: Demonstration closure: corrective action documented and reviewed for the synthetic logger-assignment deviation.

Root Cause: Rogger assignment was not completed before shipment dispatch.