

# Meridian Electronics Co. — On-Site Audit Report

|                        |                                                    |
|------------------------|----------------------------------------------------|
| <b>Facility:</b>       | Hsinchu Science Park, Taiwan                       |
| <b>Audit type:</b>     | SA8000 social compliance + ISO 14001 environmental |
| <b>Audit dates:</b>    | 2026-03-10 to 2026-03-11 (2 days)                  |
| <b>Auditor:</b>        | Meridian Assurance Partners (third-party)          |
| <b>Overall rating:</b> | Satisfactory — Low Risk                            |

## Executive Summary

This audit found Meridian Electronics Co.'s Hsinchu facility to be in substantial conformance with SA8000 social compliance and ISO 14001 environmental requirements. No major non-conformances were identified. One minor observation was raised and corrected on-site during the audit.

## Labor Practices

A review of 30 randomly sampled timekeeping records found working hours and wage payments consistent with Taiwanese labor law and the facility's stated policies. No evidence of underage workers was found; all sampled personnel files contained valid age verification documentation. Overtime was voluntary and compensated at the legally required premium rate in all sampled cases.

## Health & Safety

Personal protective equipment was observed in use at all inspected workstations on the SMT and PCB assembly lines. Fire drills are conducted quarterly per facility records, with the most recent drill logged on 2026-01-14. One observation was raised: fire extinguisher inspection tags in Building C were found to be 2 weeks overdue for their monthly check. Facility staff re-inspected and re-tagged all affected extinguishers before the audit concluded.

## Environmental

Wastewater discharge samples taken during the audit were within the facility's environmental permit limits for all tested parameters. Hazardous waste (solder dross, spent etching solution) manifests were reviewed for the preceding 6 months and reconciled correctly against licensed disposal contractor records.

## Management Systems & Documentation

The facility's internal audit and management review process was found to operate on schedule, with the most recent management review dated 2025-12-08. Corrective and preventive action (CAPA) records for the preceding 12 months show a median closure time of 9 days, well within the facility's own 30-day target. Training records for all 14 sampled line supervisors showed current certification in both SA8000 awareness and ISO 14001 procedures.

## Worker Interview Summary

18 workers were interviewed individually across day and night shifts. No worker reported unpaid wages, restricted freedom of movement, or retaliation concerns. Workers consistently described the grievance hotline and knew how to reach it, which the auditor verified by testing the hotline number.

posted at two of the three sampled workstations.

## Corrective Action Log

| Finding                                               | Severity | Due Date  | Status                     |
|-------------------------------------------------------|----------|-----------|----------------------------|
| Overdue fire extinguisher inspection tags, Building C | Minor    | Immediate | Closed — corrected on-site |

## Conclusion

Recommendation: continued certification with no follow-up audit required before the next scheduled annual audit (2027-03).