

NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-07-29**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reas	Top-20 segments (red)
1	E-53500	East bank	24.4207, 89.8133	38%	+80 m	latest pass shows rising (more open	
2	W-55500	West bank	24.3795, 89.7346	25%	+70 m	River is rising (mc pass shows a furt	
3	E-60300	East bank	24.3608, 89.8092	18%	-30 m	Bank sits on an oi but the recent pat	
4	E-61100	East bank	24.3536, 89.8096	18%	+0 m	Lost 110 m of bar	
5	W-55100	West bank	24.3825, 89.7369	18%	+10 m	Bank sits on an oi -2.2 m above the	
6	E-47100	East bank	24.4757, 89.8321	18%	+30 m	latest pass shows an outer bend / in	
7	W-54900	West bank	24.3840, 89.7380	18%	+10 m	Bank sits on an oi -0.3 m above the	
8	W-80700	West bank	24.1598, 89.6830	11%	+40 m	latest pass shows an outer bend / in	
9	W-76500	West bank	24.1955, 89.6968	11%	+10 m	Lost 70 m of bank	
10	E-61500	East bank	24.3500, 89.8098	11%	+0 m	Lost 130 m of bank over the past year; Monsoon season	
11	W-33100	West bank	24.5630, 89.6666	11%	+30 m	Bank retreated 25 m in the last 12 weeks; latest pass shows a further 30 m (unconfirmed); Lost 30 m of bank over the past year	
12	E-60700	East bank	24.3572, 89.8094	11%	+0 m	Bank sits on an outer bend / in a recess; Lost 140 m of bank over the past year	
13	W-80500	West bank	24.1615, 89.6839	11%	+10 m	Little recent retreat, but the recent pattern still raises risk; Bank sits on an outer bend / in a recess	
14	W-55300	West bank	24.3810, 89.7357	11%	-60 m	Bank height about -7.0 m above the river (DEM); Bank sits on an outer bend / in a recess	
15	W-53900	West bank	24.3920, 89.7425	11%	+20 m	Bank sits on an outer bend / in a recess; Bank retreated 15 m in the last 12 weeks; latest pass shows a further 20 m (unconfirmed)	
16	E-60500	East bank	24.3590, 89.8093	11%	-10 m	Bank sits on an outer bend / in a recess; Lost 120 m of bank over the past year	
17	E-86700	East bank	24.1452, 89.8670	11%	+0 m	Bank sits on an outer bend / in a recess; Main flowing channel is 3,143 m from the bank	
18	E-70900	East bank	24.2670, 89.8010	11%	-20 m	Bank sits on an outer bend / in a recess; Bank height about 1.3 m above the river (DEM)	
19	E-70700	East bank	24.2688, 89.8009	11%	+0 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk	
20	E-79900	East bank	24.1903, 89.8218	11%	+40 m	latest pass shows a further 40 m (unconfirmed); Bank sits on an outer bend / in a recess	

Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.