


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-08-22**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reasons)
1	E-01300	East bank	24.8356, 89.6664	38%	—	River is falling after high water; Bank sits on an outer bend / in a recess
2	E-57500	East bank	24.3859, 89.8064	38%	+410 m	latest pass shows falling after high water; Bank sits on an outer bend / in a recess
3	E-01500	East bank	24.8339, 89.6672	38%	—	Bank sits on an outer bend / in a recess; Bank height about 0.8 m above the river (DEM)
4	E-01100	East bank	24.8373, 89.6657	29%	—	River is falling after high water; Bank sits on an outer bend / in a recess
5	E-01700	East bank	24.8323, 89.6681	18%	—	Bank sits on an outer bend / in a recess; Bank height about 1.2 m above the river (DEM)
6	E-00900	East bank	24.8390, 89.6651	18%	—	River is falling after high water; Bank sits on an outer bend / in a recess
7	E-86500	East bank	24.1466, 89.8657	18%	+30 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
8	E-77500	East bank	24.2089, 89.8098	11%	+20 m	Bank sits on an outer bend / in a recess; Bank height about 2.1 m above the river (DEM)
9	E-00700	East bank	24.8407, 89.6646	11%	—	River is falling after high water; Bank sits on an outer bend / in a recess
10	E-75900	East bank	24.2221, 89.8035	11%	-10 m	Bank sits on an outer bend / in a recess; Bank height about 0.8 m above the river (DEM)
11	E-71100	East bank	24.2652, 89.8012	11%	-20 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
12	E-70900	East bank	24.2670, 89.8010	10%	-20 m	Bank sits on an outer bend / in a recess; Bank height about 1.2 m above the river (DEM)
13	W-55100	West bank	24.3825, 89.7369	10%	-3440 m	Bank sits on an outer bend / in a recess; Bank height about -2.1 m above the river (DEM)
14	W-55300	West bank	24.3810, 89.7357	7%	-3140 m	Bank sits on an outer bend / in a recess; Bank height about -6.9 m above the river (DEM)
15	E-17300	East bank	24.7128, 89.7389	7%	—	Neighbouring segments retreated 130 m on average in 12 weeks; Bank retreated 150 m in the last 12 weeks
16	E-12300	East bank	24.7572, 89.7320	7%	—	Bank height about -6.6 m above the river (DEM); Bank sits on an outer bend / in a recess
17	E-60700	East bank	24.3572, 89.8094	7%	+0 m	Bank sits on an outer bend / in a recess; Lost 140 m of bank over the past year
18	E-11500	East bank	24.7637, 89.7287	7%	—	Bank height about -7.1 m above the river (DEM); Bank sits on an outer bend / in a recess
19	E-16500	East bank	24.7197, 89.7366	7%	—	Bank sits on an outer bend / in a recess; Neighbouring segments retreated 52 m on average in 12 weeks
20	E-06300	East bank	24.8016, 89.6984	7%	—	River is falling after high water; Little recent retreat, but the recent pattern still raises risk



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.