


# NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-09-03**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

**Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.**

| #  | Segment | Bank      | Lat, Lon         | Risk | Latest pass | Why (model reas                                                                                                             | <div>Top-20 segments (red)</div>  |
|----|---------|-----------|------------------|------|-------------|-----------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|
| 1  | W-46700 | West bank | 24.4507, 89.7183 | 25%  | -10 m       | Bank sits on an oi<br>open water than 1                                                                                     |                                                                                                                      |
| 2  | E-57500 | East bank | 24.3859, 89.8064 | 18%  | -1410 m     | River is rising (mc<br>recent retreat, but                                                                                  |                                                                                                                      |
| 3  | E-44300 | East bank | 24.5007, 89.8360 | 18%  | +100 m      | latest pass shows<br>history raises risk                                                                                    |                                                                                                                      |
| 4  | E-71100 | East bank | 24.2652, 89.8012 | 11%  | +20 m       | Bank sits on an oi<br>raises risk                                                                                           |                                                                                                                      |
| 5  | E-60500 | East bank | 24.3590, 89.8093 | 11%  | +20 m       | Bank sits on an oi<br>m in the last 12 w<br>(unconfirmed)                                                                   |                                                                                                                      |
| 6  | E-86700 | East bank | 24.1452, 89.8670 | 11%  | +20 m       | Bank sits on an oi<br>m in the last 4 we<br>(unconfirmed)                                                                   |                                                                                                                      |
| 7  | W-53500 | West bank | 24.3955, 89.7432 | 11%  | +0 m        | Bank sits on an oi<br>but the recent pat                                                                                    |                                                                                                                      |
| 8  | W-54700 | West bank | 24.3855, 89.7391 | 10%  | -170 m      | Bank sits on an oi<br>m in the last 4 we                                                                                    |                                                                                                                      |
| 9  | W-13100 | West bank | 24.7348, 89.6196 | 10%  | +100 m      | latest pass shows a further 100 m (unconfirmed); Lost 110 m<br>of bank over the past year                                   |                                                                                                                      |
| 10 | W-55100 | West bank | 24.3825, 89.7369 | 10%  | -20 m       | Bank sits on an outer bend / in a recess; Bank height about<br>-2.3 m above the river (DEM)                                 |                                                                                                                      |
| 11 | E-60300 | East bank | 24.3608, 89.8092 | 10%  | +10 m       | Bank sits on an outer bend / in a recess; Lost 125 m of bank<br>over the past year                                          |                                                                                                                      |
| 12 | W-54900 | West bank | 24.3840, 89.7380 | 10%  | +0 m        | Bank sits on an outer bend / in a recess; Bank height about<br>-0.3 m above the river (DEM)                                 |                                                                                                                      |
| 13 | W-53700 | West bank | 24.3937, 89.7429 | 10%  | +0 m        | Bank sits on an outer bend / in a recess; Bank retreated 10<br>m in the last 12 weeks                                       |                                                                                                                      |
| 14 | W-53300 | West bank | 24.3973, 89.7431 | 10%  | +0 m        | Bank sits on an outer bend / in a recess; Little recent retreat,<br>but the recent pattern still raises risk                |                                                                                                                      |
| 15 | E-57100 | East bank | 24.3895, 89.8058 | 10%  | +40 m       | Bank sits on an outer bend / in a recess; latest pass shows a<br>further 40 m (unconfirmed)                                 |                                                                                                                      |
| 16 | E-77500 | East bank | 24.2089, 89.8098 | 7%   | -10 m       | Bank sits on an outer bend / in a recess; Bank height about<br>-4.6 m above the river (DEM)                                 |                                                                                                                      |
| 17 | E-38500 | East bank | 24.5521, 89.8281 | 7%   | +700 m      | Bank retreated 10 m in the last 12 weeks; latest pass shows<br>a further 700 m (unconfirmed); Past-year history raises risk |                                                                                                                      |
| 18 | E-70900 | East bank | 24.2670, 89.8010 | 7%   | +0 m        | Bank sits on an outer bend / in a recess; Past-year history<br>raises risk                                                  |                                                                                                                      |
| 19 | E-75900 | East bank | 24.2221, 89.8035 | 7%   | +0 m        | Bank sits on an outer bend / in a recess; Past-year history<br>raises risk                                                  |                                                                                                                      |
| 20 | W-35300 | West bank | 24.5454, 89.6765 | 7%   | +260 m      | latest pass shows a further 260 m (unconfirmed); Bank sits<br>on an outer bend / in a recess                                |                                                                                                                      |

Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for ‘it eroded recently’ (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.