


# NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-11-14**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

**Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.**

| #  | Segment | Bank      | Lat, Lon         | Risk | Latest pass | Why (model reasons)                                                                                                                      |
|----|---------|-----------|------------------|------|-------------|------------------------------------------------------------------------------------------------------------------------------------------|
| 1  | E-70900 | East bank | 24.2670, 89.8010 | 29%  | +40 m       | Bank retreated 10 m further 40 m (unconfirmed)                                                                                           |
| 2  | E-56300 | East bank | 24.3967, 89.8053 | 29%  | +120 m      | latest pass shows falling after high water                                                                                               |
| 3  | E-86700 | East bank | 24.1452, 89.8670 | 29%  | +50 m       | Bank sits on an outer bend in the last 4 weeks (unconfirmed)                                                                             |
| 4  | E-77500 | East bank | 24.2089, 89.8098 | 25%  | +60 m       | Bank sits on an outer bend further 60 m (unconfirmed)                                                                                    |
| 5  | E-75900 | East bank | 24.2221, 89.8035 | 25%  | +20 m       | Bank sits on an outer bend high water                                                                                                    |
| 6  | W-46900 | West bank | 24.4489, 89.7184 | 18%  | +230 m      | latest pass shows history raises risk                                                                                                    |
| 7  | E-77900 | East bank | 24.2058, 89.8118 | 18%  | +20 m       | Bank sits on an outer bend in the last 4 weeks (unconfirmed)                                                                             |
| 8  | W-10300 | West bank | 24.7593, 89.6128 | 18%  | +20 m       | River is falling after 20 m (unconfirmed)                                                                                                |
| 9  | E-64300 | East bank | 24.3249, 89.8128 | 18%  | +90 m       | latest pass shows a further 90 m (unconfirmed); River is falling after high water                                                        |
| 10 | E-01700 | East bank | 24.8323, 89.6681 | 18%  | -420 m      | River is falling after high water; Bank sits on an outer bend / in a recess                                                              |
| 11 | E-71100 | East bank | 24.2652, 89.8012 | 11%  | +10 m       | Bank sits on an outer bend / in a recess; Past-year history raises risk                                                                  |
| 12 | E-75300 | East bank | 24.2274, 89.8023 | 11%  | +40 m       | Bank retreated 20 m in the last 4 weeks; latest pass shows a further 40 m (unconfirmed); Bank height about 1.0 m above the river (DEM)   |
| 13 | E-55500 | East bank | 24.4038, 89.8063 | 11%  | +20 m       | Bank sits on an outer bend / in a recess; River is falling after high water                                                              |
| 14 | E-50100 | East bank | 24.4496, 89.8244 | 11%  | -20 m       | River is falling after high water; Little recent retreat, but the recent pattern still raises risk                                       |
| 15 | E-70700 | East bank | 24.2688, 89.8009 | 11%  | +10 m       | Bank sits on an outer bend / in a recess; Bank height about 1.6 m above the river (DEM)                                                  |
| 16 | E-88700 | East bank | 24.1316, 89.8799 | 10%  | +20 m       | latest pass shows a further 20 m (unconfirmed); River is falling after high water                                                        |
| 17 | E-47100 | East bank | 24.4757, 89.8321 | 10%  | +20 m       | Past-year history raises risk; Bank sits on an outer bend / in a recess                                                                  |
| 18 | W-53900 | West bank | 24.3920, 89.7425 | 10%  | +0 m        | Bank sits on an outer bend / in a recess; River is falling after high water                                                              |
| 19 | E-90500 | East bank | 24.1194, 89.8916 | 10%  | +140 m      | Bank retreated 10 m in the last 4 weeks; latest pass shows a further 140 m (unconfirmed); Bank height about -0.4 m above the river (DEM) |
| 20 | E-55700 | East bank | 24.4021, 89.8059 | 9%   | -10 m       | Bank sits on an outer bend / in a recess; Past-year history raises risk                                                                  |



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.