## **Mode Bus 485 Connection CN3**

CN3\_1: Ground (-Batt.)
CN3\_2: Ground (-Batt.)

CN3\_3: //// CN3\_4: ////

CN3\_5: 1500hm Resistor CN3\_6: B - 485 Mode Bus CN3\_7: A - 485 Mode Bus CN3\_8: 1500hm Resistor

Link 5-8 for termination resistor


## **CBU standard Mode Bus config.**

General Set Up\Master Slave set up

ADDRESS MODE BUS: 1 BAUD RATE: 38400bps

General Set Up\Master Slave Set UP

MASTER/SLAVE: SLAVE





## WAKE UP signal (-Batt) CN4

CN4\_2: Wake Up Signal input (to -batt)

To turn on CBU, and the mode bus, put the wake up input to -batt., not more than 0.5/1sec max

If CBU is turn off, the mode bus does not Work.

