

You are an employee of the fictitious vehicle manufacturer "OEM1". Recently, there has been an increase in reports from various TÜV organizations about irregularities in the statutory emissions testing of passenger cars. According to an initial investigation, increased emissions of CO occur in engine control units that use a special software version. The German Federal Motor Transport Authority has already informed the company's management about these irregularities. They are investigating this case on behalf of management and have already requested the parts lists of the engines from the 2008-2016 production years from the affected engine manufacturers. All affected control units "T2" were installed in vehicles with gasoline engines and produced by the control unit manufacturer "202" in the plant "2022" in the period from April 31, 2009 to November 31, 2014. Also affected are units with production numbers "2-201-2011-1250" to "2-201-2011-19500" according to information from manufacturer "201". Identify all affected vehicles of your make and the municipality in which they were registered. The "T2" control units are installed in all "OEM1" brand engines. These engines can be selected by the customer as an equipment feature of the "Type11" or "Type12" vehicle types. You should identify affected vehicles and isolate parts, component, and automotive manufacturers that have installed affected components in their vehicles from the available data.

Zuletzt geändert: Freitag, 17. Juli 2026, 02:13