# u-blox GNSS Sensor and VCP Device Driver v2.32

Release note

### **Abstract**

Release note containing general information, features, improvements, changes and known limitations for the u-blox GNSS Sensor and VCP Device Driver v2.32.

www.u-blox.com

UBX-16031033 - R01







### **Document Information**

**Title** u-blox GNSS Sensor and VCP Device Driver v2.32

**Subtitle** 

**Document type** Release Note

**Document number** UBX-16031033

**Revision and date** R01 15-Dec-2016

**Document status** Production Information

### **Document status explanation**

Objective Specification Document contains target values. Revised and supplementary data will be published later.

Advance Information Document contains data based on early testing. Revised and supplementary data will be published later.

Early Production Information Document contains data from product verification. Revised and supplementary data may be published later.

Production Information Document contains the final product specification.

u-blox reserves all rights to this document and the information contained herein. Products, names, logos and designs described herein may in whole or in part be subject to intellectual property rights. Reproduction, use, modification or disclosure to third parties of this document or any part thereof without the express permission of u-blox is strictly prohibited.

The information contained herein is provided "as is" and u-blox assumes no liability for the use of the information. No warranty, either express or implied, is given with respect to, including but not limited to, the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, please visit www.u blox.com. Copyright © 2016, u-blox AG.

u-blox® is a registered trademark of u-blox Holding AG in the EU and other countries.



# **Contents**

1 Introduction	4
1.1 Installer Files	4
1.2 Components	4
1.3 Released Documentation	4
2 Features	5
2.1 Supported Microsoft Windows versions	
2.2 Windows Hardware Certification	5
2.3 Supported u-blox GNSS receivers	
3 Improvements and Changes	6
3.1 Version 2.32.	
3.2 Version 2.31	
3.3 Version 2.30	
3.4 Version 2.24	6
3.5 Version 2.23	6
4 Known Limitations	7
4.1 Known Issues.	



### 1 Introduction

This document provides the release note for the u-blox GNSS Sensor and VCP Device Driver v2.32.

### 1.1 Installer Files

The installer files for the drivers are:

- ubloxGNSS\_sensorDeviceDriver\_windows\_3264\_v2.32.exe
- ubloxGNSS\_vcpDeviceDriver\_windows\_3264\_v2.30.exe

### 1.2 Components

The Sensor Device Driver installer contains the following components:

- USB GNSS Sensor Device Driver
- Radio Manager (Windows 8 and above)

The VCP (Virutal COM Port) Device Driver installer contains the following components:

• Virtual COM Port Device Driver

### 1.3 Released Documentation

- Public Release Notes (UBX-16031033)
- u-blox GNSS Sensor and VCP Device Driver User Guide (UBX-15022397)



### 2 Features

### 2.1 Supported Microsoft Windows versions

The following Windows version are supported:

- Windows 7, 32- and 64-bit
- Windows 8, 32- and 64-bit
- Windows 8.1, 32- and 64-bit
- Windows 10, 32- and 64-bit

### 2.2 Windows Hardware Certification

The Sensor Device Driver is certified and signed for the following Windows versions:

- Windows 7, 32- and 64-bit
- Windows 8.1, 32- and 64-bit
- Windows 10 (Build 14393, August 2016 update), 32- and 64-bit

The VCP Device Driver is certified and signed for the following Windows versions:

- Windows 7, 32- and 64-bit
- Windows 8.1, 32- and 64-bit
- Windows 10, 32- and 64-bit

### 2.3 Supported u-blox GNSS receivers

The following u-blox GNSS receivers are supported:

•			
Receiver generation	Product ID	Vendor ID	Device name (shown in Device Manager)
u-blox 5	0x01A5	0x1546	u-blox 5 GPS and GALILEO Receiver
u-blox 6	0x01A6	0x1546	u-blox 6 GPS Receiver
u-blox 7	0x01A7	0x1546	u-blox 7 GPS/GNSS Receiver
u-blox 8/M8	0x01A8	0x1546	u-blox GNSS Receiver



# 3 Improvements and Changes

### 3.1 Version 2.32

Sensor Device Driver:

- Satellite information (signal strength, azimuth, elevation, count etc.) now passed to sensor platform.
- Updates to leap second table.

VCP Device Driver:

• No changes, still at version v2.30.

### 3.2 Version 2.31

Sensor Device Driver:

- Re-signed for Windows 7, 8, and 10 (build 14393, August 2016 update) with expiry date increased to 05-Jan-2018.
- No binary changes.

VCP Device Driver:

• No changes, still at version v2.30.

### 3.3 Version 2.30

Sensor Device Driver:

- Rebuilt with Visual Studio 2013 Update 4.
- Re-signed for Windows 7, 8, and 10 (build 14393, August 2016 update).
- Co-Installer to initiate VCP Device Driver installation removed.

VCP Device Driver:

- Version increased to v2.30.
- DUA from v2.24, no binary changes.

### 3.4 Version 2.24

- Fixed the date issue in the Sensor driver's .inf file. Version 2.23 had the wrong year (2015 instead of 2016).
- Enable the VCP driver for all languages.

### 3.5 Version 2.23

- Fixed an issue in the Sensor driver's automatic installation of the VCP driver. VCP installation is now more seamless.
- Enable the sensor driver for all languages.



# **4 Known Limitations**

### 4.1 Known Issues

• Some content of NMEA messages may violate the NMEA standard.



## **Contact**

For complete contact information visit us at www.u-blox.com.

North, Central and South America

#### u-blox America, Inc.

+1 703 483 3180 Phone: E-mail: info\_us@u-blox.com

#### **Regional Office West Coast**

+1 408 573 3640 Phone: info\_us@u-blox.com E-mail:

#### **Technical Support**

+1 703 483 3185 Phone: support\_us@u-blox.com E-mail:

### Headquarters

Europe, Middle East, Africa

#### u-blox AG

+41 44 722 74 44 Phone: E-mail: info@u-blox.com support@u-blox.com Support:

#### Asia, Australia, Pacific

#### u-blox Singapore Pte. Ltd.

+65 6734 3811 Phone: E-mail: info\_ap@u-blox.com support\_ap@u-blox.com Support:

### **Regional Office Australia**

+61 2 8448 2016 Phone: info\_anz@u-blox.com E-mail: support\_ap@u-blox.com Support: Regional Office China (Beijing)

+86 10 68 133 545 Phone: info\_cn@u-blox.com E-mail: support\_cn@u-blox.com Support:

### Regional Office China (Chongqing)

+86 23 6815 1588 E-mail: info\_cn@u-blox.com support\_cn@u-blox.com Support: Regional Office China (Shanghai)

#### +86 21 6090 4832 Phone:

E-mail: info cn@u-blox.com support\_cn@u-blox.com Support: Regional Office China (Shenzhen) +86 755 8627 1083 Phone:

E-mail: info\_cn@u-blox.com support\_cn@u-blox.com Support:

### **Regional Office India**

+91 80 4050 9200 Phone: E-mail: info\_in@u-blox.com support in@u-blox.com Support:

#### Regional Office Japan (Osaka)

+81 6 6941 3660 Phone: info\_jp@u-blox.com F-mail: Support: support\_jp@u-blox.com

Regional Office Japan (Tokyo) Phone: +81 3 5775 3850 info\_jp@u-blox.com E-mail: support\_jp@u-blox.com Support:

### **Regional Office Korea**

+82 2 542 0861 info\_kr@u-blox.com Phone: E-mail: support\_kr@u-blox.com Support:

### Regional Office Taiwan

+886 2 2657 1090 Phone: info\_tw@u-blox.com E-mail: support\_tw@u-blox.com Support: