

## ПРОФИЛЬ ДЛЯ ПОРОГОВ

		Порог	"U		
2066	42,5	S=1514 x8.cm M= 0,41kz P= 94 mm	3058	38	S=1402x8;см М=0,38кг Р=109мм
2122-1	9 40	S= 1094x8cm M= 0,296 k2 P= 159,1 mm	3099	18	S=1093x6cm M=0,296k2 P=184,4mm
2123	8 30 .	S= 0.817k6.cm M=0.222 kz P=121,1 mm	3478	30	S=0,655xåcm M=0,178kz P=69,4mm
2160	. 83	S= 2,938x6,cm M= 0,796x2 P= 214,8mm	3842	S C 81	S=3,075 k0.cm M= 0,833 k2 P= 316,7 mm
2288	30,5	S= 0,724x8.cm M= 0,196x2 P= 69,7mm	3879	<b>1</b> 1 7 × 58	S=1,711 x8.cm M= 0,464 k2 P= 246,3 mm
2317	25	S=0.573x8.cm M=0,155k2 P=55,4mm	3920	41	S= 0,807 x5.cm M= 0,219 k2 P= 102 mm
2798	55	S=2,083x6;cm M=0,565k2 P=180,5mm	3921	30,2	S= 0,579 kbcm M= 0,157 kz P= 100,6 mm
3057	36	S=158kb.cm M=0,428kz P≈88,6mm	3922	30	S= 0,484 xb.cm M= 0,131kz P= 74,7 mm

		Порог	U		
0696	55	S= 1.717x0.cm M= 0.465 kz P= 179.5m	1448	200	S=0,76x0.cm M=0,207kz P=95mm
0697	215	S= 1.896d.cm M= 0.465 kz P= 2027im	1495	20	S=0,91k0.cm M=0,247 kz P=130mm
0698	534	S= 1396x0.cm M= 0.379 kz P= 150.1m	1496	39.6	S=1,01k0.cm M=0,273k2 P= 139mm
0742	255	S= 0.388 k0.cm M= 0.105 k2 P= 59.3 mm	1829	36	S= 1592xtl.cm M=0,431 kz P= 88,6 mm
0743	292	S=0.466 кбли М=0.126 кг Р=69.79 ми	1834	28,6	S= 0,322x6.cm M= 0,09 kz P= 69,5mm
0744	36.2	S= 0.615 kb.cm M= 0.167 kz P= 89.59mm	1960	51	S=1249x8.cm M=0,339 kz P=131,6 mm
0756	28	S= 0.467x0.cm M= 0.127 kz P= 75.8 mm	1996	20	S=0,662x0.cm M=0,179 k2 P=67,9mm
0895	14.0	S= 5553 k0.0H M= 1505 k2 P= 420.7 HM	2065	34,5	S=1,194x0.cm M=0,324k2 P=78,3mm

		Порог	?U		
3923	20	S= 0,318 x0.cm M= 0,086x2 P= 57,6 mm	4113	- 41 -	S= 0,866 кб.см М= 0,235 кг Р= 138 мм
3924	25	S= 0,387 kbcm M= 0,105kz P= 68,3 mm	4114.	45,5	S= 0,967 x6.cm M= 0,257 k2 P= 173,4mm
3925	15	S= 0.267 x6cm M= 0.072x2 P= 48,3 mm	4115	40	S= 0,639 kB.cm M= 0,173 kz P= 98,8mm
3926	30	S= 0.943 kb.cm M= 0.256k2 P= 141 mm	4116	23,5	S= 0,91 kb.cm M= 0,247 k2 P= 137,2 mm
3927	40	S= 1066 кб.см М= 0,289кг Р= 150,6 мм	4117	47,6	S= 0,966 x6.cm M= 0,262 k2 P= 149 mm
3928	50	S= 0,912 kB.cm M= 0,247k2 P= 124,1 mm	4118	Si 51	S= 1,345 кб.см М= 0,365 кг Р= 220,7 мм
3929	40	S= 0,711 kbcm M= 0,193 kz P= 92,9 mm	4134	68,7	S= 1844 x0.cm M= 0.5 x2 P=189.6 mm
3930	22	S= 0,506 kB.cm M= 0,137 kz P= 87,3 mm	4135	44,8	S= 1539 x0.0M M= 0,417 kz P=163,9 mm

		Порог	U		
4136	95,1	S= 2,796 x0.cm M= 0,758 kz P=255,2 mm	0112	SH 6	S=6.12 кб.сн М=1,7 кг Р=210 мм
4751	23,8	S= 1,093 k0.cm M= 0,296 kz P=143,3 mm	0529	85	S=0.457 k0.cm M=0.124 kz P=74 mm
4773	38,5	S= 1,466 k0,cm M= 0,397 kz P=155,2 mm	1399	25	S=0.828 kÖ.CM M=0.224 k2 P=78 mm
5310	16	S= 0,52 k0.cm M=0,141 k2 P=75,2 mm	1400	2 5	S=0.768 kb.cm M=0.208 k2 P=72 mm
5896	37,7	S= 0,628 k0.cm M=0,17 kz P=101,6 mm	1727	5 60	S=1772 k0.cm M=0.480 kz P=135.2 mm
5919	09	S= 1,653 k0.cm M=0,448 kz P=208,4 mm	1805	40	S=0.509 k0.cm M=0.138 k2 P=88.5 mm
6144	45	S= 1,191 kÖ.cm M=0,323 k2 P=176,6 mm	1822	245	S=0.445 kt/cm M=0.121 kz P=68.5 mm
6223	\$	S= 1433 кб.сн М=0,388 кг Р=196,4 мм	1997	3	S=0.581 x0.cm M=0.158 x2 P=87.4 mm

		Порс	1ZU		
2048	22	S=0559 xbcm M=0.152 x2 P=63.2 mm	2212	293	S=0.612 kbcm M=0.169 kz P=97.2 mm
2055	π5	S=1285 kB.cm - M=0.348 kz - P=152.5 mm	2213	204	S=1018 кб.см М=0,276 кг Р=14,26 мм
2075	58,6	S=0.993 xb.cm M=0.269 xz P=119.1 mm	2245	30	S=0.488 kb.cm M=0.132 k2 P=71.04 mm
2076	23	S-0.76 xb.cm M=0.206 kz P=97.7 mm	2246	38	S=0.488 x6.cm M=0.132 x2 P=71.04 mm
2105	50	S=0.67 kbcm M=0.182 kz P=105.3 mm	2254	80	S=3.098 kbcm M=0.840 kz P=197.2 mm
2209	24	S= 0x5684 M= 0x96 P= 7x81	2257	5.8	S=1067 kbcm M=0.289 kz P=128.9 mm
2210	38,5	S=0.614 kBcM M=0.166 kz P=1217 MM	2276	31	S=0.135 kt/mm M=0.367 kz P=151 mm
2211	34	S-0562 x0.04 M=0.152 x2 P=120.3 mm	2282	8	S-1067 kb,mm M=0.453 kz P=111.1 mm

		Порог	y	
2288	20 20	S=195 x6744 M=0.529 k2 P=1793 mm		
2295 u 2295-2		S=0.591 kb/m M=0.16 kz P=68.9 mm		

		Порога	y .		
0036	265	S= 0.519 k0.0m M= 0.141 k2 P= 70.0 mm	0455 u 2480	×	S= 0,963 kb.cm M= 0,261
0438 u 2400	× 5	S= 2,145 x0.cm M= 0,581	0460	40	S= 0.583 k0.cm M= 0.158
0440	2	S= 0.842x0.cm M= 0.228 kz P= 78.3 mm	0461	373	S= 0.628x0.cm M= 0.170
0445	63	S= 2.469x0.cm M= 0.669 kz P= 172.0 mm	0462 u 1982	2.7	S= Q.411 x0.cm M= Q.111 K2 P= 59.9 MH
0450 u 0562	***************************************	S= 0.622x8.cm M= 0.169 kz P= 75.9 mm	0463	23	S= 0.640 xb.cm M= 0.173
0451 u 0561	4.8	S= 0.462 x0.cm M= 0.125	0464	30	S= 0.571 kbcm M= 0.155 k2 P= 9103 mm
0453 u 2315	2 25	S= 0527 x0.cm M= 0.143	0465	5.6	S= 1,056 x0,cm M= 0,286
0454	9	S=1332 x0.cm M=0.361 x2 P=87.6 mm	0466	255	S= 0.387 kb.cm M= 0.105 k2 P= 59.7 mm

		Порог	ru		
0467	292	S= 0.466 k0.cm M= 0.126	0475	30	S= 0.466x0.cm M= 0.126
0468	<u>%5</u>	S= 0.615 x0.cm M= 0.166	0476	39.4	S= 0.736x0,cm M= 0.199 k2 P= 92.25 mm
0469	23	S= 1,000 kb.cm M= 0,271 kz P= 127.1 mm	0477	54	S= 1398 kbch M= 0.378 kz P= 193.13 mm
0470 u 1976	80	S= 1,147 k0.cm M= 0,311 k2 P= 180.5 mm	0478	20	S= 0.399xt.ch M= 0.108 k2 P= 817 mm
0471	122	S= 0.723 кблон М= 0.196 кг Р= 70.0 мм	0479	445	S= 0.801 kb.ch M= 0.216
0472	33	S= 0,557 k0,cm M= 0,150 k2 P= 79,7 mm	0480	31	S= 0.629 k0.ch M= 0.170 k2 P= 77.8 mm
0473	25	S= 0,392 kb.cm M= 0,106	0481	24	S= 0.574 kb.ch M= 0.155
0474	35	S= 0.276 x0.cm M= 0.07	0482	55	S= 1.099 kb.cm M= 0.297 kz P= 130.61 mm

_			Порог	U		
	0483	2	S= 0.585 x0.cm M= 0.158	0491	28	S= 0.525 kb.ch M= 0.142 kz P= 94.79 mm
	0484	2 24	S= 0.469 k0.cm M= 0.127 k2 P= 67.8 mm	0492	33	S= 0.662 kb.cm M= 0.179
	0485	214	S= 0.316 k0.cm M= 0.085	0493	8	S= 0.29 k0.cm M= 0.078 k2 P= 61.164mm
	0486	20	S= 0.398 k0.cm M= 0.108	0494	- X	S= 1,005 кб.см M= 0,271 кг P= 126,85мм
	0487	372	S= 0.586 x6.cm M= 0.158	0495	40	S= 0.877кб.сн М= 0.237 кг Р= 129 нн
	0488	214	S= 0.323 kb.cm M= 0.087	0496	2 77	S= 0.544 k0.cm M= 0.147 k2 P= 92.18 mm
	0489	15	S= 0.906 x8.cm M= 0.245	0497	2	S= 0.639 кбли M= 0.173 кг P= 109.8 мм
	0490	9,3	S= 0.478 кб.сн М= 0.129 кг Р= 86.77 мм	0498	28	S= 0.628 кбли М= 0.170 кг Р= 105.6 мм

		Порог	U		
0499	22	S= 0.907 kb.cm M= 0.245 kz P= 138.2 mm	0507	2	S= 0.896 kb.cm M= 0.242 kz P= 123.92mm
0500	80	S= 1498 kb.cm M= 0.405 kz P= 180.1 mm	0508	22	S= 0.562 kb.cm M= 0.152 kz P= 82.9 mm
0501	10.9	S= 0.866 kb.cm M= 0.234 kz P= 160.8 mm	0547	17 60	S= 2469 kfloh M= 0.669 kz P= 172.0 hm
0502	33	S= 0.933 k0.cm M= 0.252 k2 P= 159.4 mm	0548 u 2283	8	S= 1,637 kb,cm M= 0,444 k2 P= 109,4 mm
0503	, m	S= 0.723 kbcm M= 0.195	0549 u 2284	× ×	S= 4,064 kt/cm M= 1,101
0504	132	S= 0,935 kb.cm M= 0,252 kz P= 107,88mm	0551	F 3	S= 1354 kb.cm M= 0.367 k2 P= 1510 mm
0505	373	S= 0.787 xb.cm M= 0.213	0552 u 2273	\$ 2	S=0.659 k0.cm M=0.179 kz P=82.9 mm
0506	293	S= 0,529 kb.cm M= 0,143	0560	***************************************	S-0.659 kb.cm M=0,179 k2 P=82.9 mm