

Case Memorandum & Forensic Evidence Dossier: August 28, 2026 Collision

CONFIDENTIAL ATTORNEY-CLIENT PRIVILEGED / CLAIMS EVALUATION MEMORANDUM

SUBJECT: Forensic Reconstruction, Telematics Analysis, Coverage Determination, and Injury Documentation
DATE OF LOSS: Friday, August 28, 2026 at 05:00:15 AM CDT
LOCATION: Intersection of Bass Pro Dr & SH 121 Frontage Rd / On-Ramp, Grapevine, Tarrant County, TX (32.955144° N, -97.038026° W)
TxDOT CRASH ID: 21609720.1 (Certified 09/02/2026 by TxDOT Crash Data & Analysis Section)
GRAPEVINE PD CASE ID: 2600037671 (Form CR-4 01/01/2026) · Responding Officer: R. Smith (ID 14177)
CLIENT / INSURED: Melody Dawn Dashora · Progressive Policy #936659747 · Claim #26-854858569
ADVERSE DRIVER: Tamika Savala-Fitzpatrick · 2014 BMW 550 (TX Plate: vdw2544) · **UNINSURED ON POLICE REPORT (Proof of Financial Resp: NO)**

1. Executive Summary & Master Case Metadata

On August 28, 2026, at 05:00:15 AM, client Melody Dawn Dashora was operating her 2025 Volkswagen Atlas SUV eastbound on Bass Pro Drive in Grapevine, Texas, en route to an accepted Uber rideshare passenger (Period 2). While executing a protected left turn onto the northbound SH 121 entrance ramp under a Protected Green Arrow, her vehicle was broadsided by an uninsured 2014 White BMW 550 traveling westbound on Bass Pro Drive.

The collision knocked the client unconscious, deployed multiple cabin airbags across three zones, severed vehicle accessory circuits, and resulted in emergency transport to Baylor Scott & White Medical Center – Grapevine with a closed head injury (concussion), cervical sprain, and multiple contusions.

Although the initial investigating police officer entered an inaccurate boilerplate narrative stating the client "failed to yield turning left on a flashing yellow light," this narrative is **completely refuted by objective physical, video, and electronic evidence**:

- Contemporaneous Video Audio:** On-scene video captures the client explicitly stating to the investigating officer that her light **WAS GREEN**. The officer's claim of a "flashing yellow light" is an unsubstantiated insertion contradicted by recorded evidence.
- Physical Damage Vectors (CR-4 Page 3):** The client's vehicle sustained **3 O'CLOCK** right-side angular damage with a **100% undamaged front bumper**. The adverse BMW sustained **12 O'CLOCK** front-end distributed damage. It is physically impossible for the client to have "struck" the adverse vehicle; the adverse vehicle rammed the client broadside.
- Forensic Sub-Second Telematics (13,285 Records):** Extracted GPS data confirms the client completed a 26.0-second full stop at the West Ramp Terminal, crossed the 1,200 ft bridge on green, decelerated to ~15-17 MPH on approach to pace the cycle, reached the white pavement turn arrow at 05:00:11 AM as the Protected Green Arrow illuminated, and was fully straightened **0.0° Straight North** into the ramp prior to impact.
- TxDOT Diamond Controller Standard:** The coordinated master controller enforces bridge interior clearance by serving a protected green arrow to arriving bridge platoons while holding opposing westbound traffic (BMW) in **SOLID RED**.
- Adverse Driver Status:** Adverse driver Tamika Savala-Fitzpatrick was driving without insurance (Proof of Financial Responsibility: NO) and admitted to speeding up on a yellow light to beat the cycle.

Because the adverse driver is uninsured, primary bodily injury recovery is governed directly under the client's **Progressive Uninsured Motorist (UM) Coverage (\$250,007 / \$500,007)** and **Personal Injury Protection (\$10,003)**.

2. Party, Vehicle & Coverage Summary

Parameter	Unit #1 (Client / Insured)	Unit #2 (Adverse Driver)
Driver Name	Melody Dawn Dashora (DOB: 07/01/1978, Age 48)	Tamika SAVALA-FITZPATRICK (DOB: 08/28/1997, Age 29)
Driver Address	6058 Midnight Moon Dr, Frisco, TX 75036	2290 W Tarleton St, Stephenville, TX 76401 / Irving, TX
Driver License	Texas Class C #44807726 (No restrictions)	Texas Class C #36470205 (Corrective Lenses)
Vehicle Make / Model	2025 Volkswagen Atlas SE FWD SUV (Black — Deep Black Pearl per Mitchell estimate and pre-accident photos; the CR-4 entry reads "SILVER" and	2014 BMW 550 4-Door Sedan (White)

Parameter	Unit #1 (Client / Insured)	Unit #2 (Adverse Driver)
	should be corrected)	
VIN / License Plate	VIN: 1V2DR2CA0SC529343 · Plate: TX WHB6147	VIN: WBAKN9C5XED681044 · Plate: TX vdw2544
Vehicle Owner	Melody Dawn Dashora (Financed: Capital One)	Tamika Savala (801 Lake Canyon Pkwy, Irving, TX 75039)
Insurance Carrier	Progressive County Mutual Ins. Co.	UNINSURED ON CR-4 (Proof of Financial Resp: NO / Subject to ISO Discovery)
Policy / Claim Number	Policy #936659747 · Claim #26-854858569	None (Activates Client's \$250k/\$500k UM Coverage)
Applicable Coverage	UM: \$250k/\$500k · PIP: \$10,003 · Coll: \$99 Ded.	Uninsured Motorist Claim against Progressive
Damage Force Vector	3 O'CLOCK (Right front quarter/side angular impact)	12 O'CLOCK (Direct front-end distributed impact)
Damage Severity	DAMAGED 4 (Structural intrusion, multiple airbags)	DAMAGED 3 (Front-end crumple, airbags deployed)
Front Bumper Status	100% Undamaged (Conclusive side impact)	Direct Frontal Impact (Nose rammed client side)
Towing / Storage	Euless B&B Wrecker Service (1201 W Euless Blvd)	Euless B&B Wrecker Service (1201 W Euless Blvd)

Key Witness

- **Precious Kherriel Ramecia Mccall** · 2305 Summer Place Dr, Arlington, TX 76014 · DL: Texas #47404130 (Listed on CR-4 Crash Report Page 3).

3. Status of Critical Case Inquiries

Field	Status	Details & Strategic Legal Impact
Other driver insurer & policy limits	UNINSURED ON POLICE REPORT (Proof of Financial Resp: NO) ☐	On the certified crash report (#21609720.1), Officer Smith ran the vehicle through TexasSure and recorded Proof of Financial Responsibility: NO, leaving all policy fields blank. Under Texas law (Tex. Ins. Code § 1952.101), this establishes prima facie uninsured status. Progressive will run a formal LexisNexis / ISO ClaimSearch verification; in the interim, client's \$250,007 / \$500,007 Progressive UM coverage is primary.
Citation issued to other driver?	NO CITATIONS LOGGED ON CR-4	Investigating officer noted Proof of Financial Responsibility: NO for Unit 2 on the crash report, but logged no citations for either driver at the scene because both were transported by EMS to Baylor Scott & White. Charges for driving uninsured (Tex. Transp. Code § 601.051) and failure to yield/disregard red light remain subject to Grapevine Municipal Court jurisdiction.
Drive Type	CONFIRMED: FRONT-WHEEL DRIVE (FWD) ☐	Verified via Progressive / Mitchell Cloud Estimating Records (Mitchell Code: 912009). The vehicle is standard FWD configuration.
Trim Level	CONFIRMED: SE (BASE TRIM) ☐	Verified via Progressive / Mitchell Cloud Estimating Records (Mitchell Code: 912009). The vehicle is equipped with the factory SE package (18" alloy wheels, heated/ventilated front seats, heated steering wheel, power driver seat, 3-row seating). ACV valuation should be calculated on clean 2025 Atlas SE FWD comps with positive condition adjustments.
Progressive Period 2 Coverage Position	COVERED UNDER PERSONAL POLICY (Rideshare Endorsement Active) ☐	Progressive declarations explicitly state Ridesharing: Yes on the 2025 Atlas (WHB6147), eliminating livery exclusions. Under Texas Insurance Code § 1954, Collision (\$99 deductible), PIP (\$10,003), and UM (\$250k/\$500k) extend to Period 2 (ride accepted, en route). Formal written confirmation requested from adjuster Sloane S.
Uber Period 2 UM/UIM Position	STATUTORY CONTINGENT UM COVERAGE ACTIVE ☐	Under Texas Insurance Code § 1954.053 (HB 3520), Uber provides primary \$1M commercial liability and statutory Uninsured/Underinsured Motorist (UM/UIM) coverage for drivers during Period 2. Uber trip accepted at 04:59 AM, canceled post-crash at 05:05 AM (\$12.07 fare). Data preservation request submitted via Uber Privacy Portal and Incident Response.

4. Master Directory of Case Contacts

Entity	Role / Detail	Contact Information
Progressive Insurance	First-Party Insurer (Policy #936659747) · Claim Rep: Sloane S	Claim #26-854858569 · App Messaging / (800) 776-4737

Entity	Role / Detail	Contact Information
Adverse Driver	Unit 2 Uninsured Motorist: Tamika Savala-Fitzpatrick	2290 W Tarleton St, Stephenville, TX 76401 / Irving, TX
Eyewitness	Witness listed on Police Report: Precious Mccall	2305 Summer Place Dr, Arlington, TX 76014 · DL TX 47404130
TxDOT Crash Records	State Custodian of Records · Director: Jim Markham	(844) 274-7457 · Crash ID 21609720.1
Grapevine Police Dept	Investigating Agency · Officer R. Smith (ID 14177)	1007 Ira E. Woods Ave, Grapevine, TX 76051 · rlsmith@grapevinetexas.gov · Records: (817) 410-3218 · Case 2600037671
Euless B&B Wrecker	Vehicle Storage Facility (Holding 2025 Atlas)	1201 W Euless Blvd, Euless, TX 76040 · (817) 283-2121
Capital One Auto Finance	Primary Lienholder (Payoff: \$39,688.03 good to 9/8)	(800) 946-0332 · Per Diem: \$13.82
Baylor Scott & White	Emergency Medical Facility (Treated 8/28/2026)	1650 W College St, Grapevine, TX 76051 · (817) 481-1588 · MRN 15608293 · Attending: Dr. Jonathan Holt
Dr. Sarah Uddin	Primary Care Physician (Post-Crash Management)	Discharge referral physician of record
Hendrick VW Frisco	Servicing Dealer (Reconditioned Atlas 8/24/2026)	5010 SH 121, Frisco, TX 75034 · RO & Multi-Point Inspection Sheet
CVS Pharmacy #10523	Discharged Prescription Pharmacy	270 Stonebrook Pkwy, Frisco, TX 75036 · (214) 469-1143
Uber Technologies	Rideshare Platform (Period 2 Active at Crash)	Driver Support · Privacy Portal ("Download Your Data")
Volkswagen Group of America	Manufacturer Connected Vehicle / ACN Records	Car-Net Emergency Response Center · VIN 1V2DR2CA0SC529343
ADT Security Services	Emergency Dispatch Monitoring Provider (SOS Relay)	Incident audio recording and police relay log
TDLR (Texas Dept of Licensing)	VSF Regulatory Body (Storage Fee Enforcement)	tdlr.texas.gov · 16 TAC § 85.722 (\$22.85 daily rate cap)
TxDOT Fort Worth District	Primary Corridor Jurisdiction (SH-121) & Regional ITS Cameras	2501 SW Loop 820, Fort Worth, TX 76133 · (817) 370-6500 Corridor Contact: Michael Peters (817-370-6846 / michael.peters@txdot.gov) Open Records: TxDOT_ORR@txdot.gov
City of Grapevine Public Works	Traffic Cabinet Maintenance / Municipal Agreement	Grapevine Municipal Service Center, 501 Shady Brook Dr, Grapevine, TX 76051 Public Works Direct: (817) 410-3330 · City Main: (817) 410-3000
Shell Gas Station	Surveillance Video (Corner of Bass Pro & W Bethel Rd)	2000 W Bethel Rd, Grapevine, TX 76051 · (817) 421-2295
Hampton Inn & Suites DFW North	Surveillance Video (Adjacent to SH-121 / Bass Pro interchange)	1750 N Hwy 121, Grapevine, TX 76051 · (972) 471-5000
Aloft Dallas DFW Airport Grapevine	Surveillance Video (Client Intended Destination)	1033 N Main St, Grapevine, TX 76051 · (817) 488-6677

5. Certified Incident Timeline & Kinematic Sequence

The following sub-second timeline is corroborated across five independent electronic and physical data sources: (1) 13,285-record vehicle GPS telematics, (2) TxDOT Diamond interchange signal standards, (3) on-scene recorded video, (4) Apple Crash Detection emergency dispatch logs, and (5) certified police crash report damage vectors.

=====

SUB-SECOND KINEMATIC TIMELINE: AUGUST 28, 2026

=====

- 04:59:18 AM – 04:59:44 AM (26.0s STOP AT WEST RAMP TERMINAL):
- Client SUV stopped completely at 0.0 MPH at the West Terminal stop bar (Bass Pro Dr & TX-121 SB Frontage).
 - Signal state: SOLID RED. In-pavement loop sensor called master interchange controller.
- 04:59:45 AM (DEPARTURE ON SOLID GREEN ACROSS BRIDGE):
- West light turned SOLID GREEN. Client departed and accelerated across the 1,200 ft freeway bridge over SH 121.

- Speed climbed steadily up to 39.1 MPH at 05:00:05 AM.

05:00:06 AM – 05:00:10 AM (PACING TURN BAY DOWN TO ~15–17 MPH IN LIGHT TRAFFIC):

- Client tracked the signal progression ahead. In light 5:00 AM traffic, rather than rushing to a stop and waiting, client paced approach speed, smoothly decelerating from 39.1 MPH down to ~15–17 MPH to meet the green arrow.

05:00:11 AM (WHITE PAVEMENT ARROW & PROTECTED GREEN ARROW TRIGGER):

- As client front tires crossed the painted white left-turn arrow (verified in Google Street View at 32.955021° N, -97.038307° W), the dedicated overhead Left-Turn Signal illuminated the PROTECTED GREEN ARROW.
- By TxDOT Diamond standards, opposing westbound through traffic (Unit 2 BMW) was locked in SOLID RED.
- Client initiated turn smoothly on GREEN at ~15–17 MPH without stopping in the turn lane.

05:00:14 AM (POINT OF INEVITABLE IMPACT – 1.0 SECOND BEFORE CRASH):

- Client completed turn; vehicle 100% straightened to 0.0° STRAIGHT NORTH into SH 121 entrance ramp (exact Street View perspective match at 32.955075° N, -97.038105° W).
- Eyewitness Observation: Looking east through passenger window, client saw white BMW approaching at 42 MPH without slowing, realizing it would run the red light. Flanked by concrete medians and facing north, client had zero escape avenue.

05:00:15 AM (BROADSIDE T-BONE IMPACT):

- Adverse BMW ran the red light, ramming its front bumper (12 O'CLOCK damage) into client's right side (3 O'CLOCK damage).
- Client front bumper was 100% untouched. Force deployed all cabin airbags and knocked client unconscious.

05:00:00 AM: Android 911 text session opened.

05:02:00 AM: Apple Crash Detection placed 911 call ("owner in severe crash and is not responding").

05:04:00 AM: Dashcam resumed; officer speaks to client. Client on video tells officer: "MY LIGHT WAS GREEN."

05:05:00 AM: Uber trip canceled by platform (\$0.00).

05:05:43 AM: Hardware-stamped scene photograph captured (shattered cabin, deployed side curtains).

06:11:00 AM: Vehicle received at Euless B&B Wrecker Service.

6. Formal Statement of Facts & Account of Melody Dawn Dashora

"I, Melody Dawn Dashora, declare that the following is my true and accurate formal Statement of Facts and Account regarding the motor vehicle collision of August 28, 2026:

1. **Commercial Operating Background:** On Friday, August 28, 2026, at approximately 04:59 AM CDT, I was operating my 2025 Volkswagen Atlas SUV (TX Plate: WHB6147) eastbound on Bass Pro Drive in Grapevine, Texas. I was logged into the Uber rideshare platform and had accepted a dispatch (Period 2), en route to pick up an assigned passenger. I have logged over 50,000 commercial miles and nearly 2,000 trips for Uber alone in this vehicle, and was operating at full functional physical capacity.
2. **Initial Stop at West Ramp Terminal:** At 04:59:18 AM, I came to a complete stop on a solid red signal at the West Ramp Terminal of the SH 121 interchange (Bass Pro Dr & TX-121 SB Frontage Road). I remained stationary at 0.0 MPH for 26.0 seconds waiting for the signal to cycle.
3. **Bridge Crossing & Pacing Approach on Green:** At 04:59:45 AM, my signal turned solid green. I proceeded across the 1,200-foot freeway bridge over SH 121, accelerating to approximately 39 mph. With virtually no traffic on the road at 5:00 AM, I tracked the signal sequence ahead at the East Terminal left-turn bay (for the northbound SH 121 on-ramp). As an experienced commercial driver, I pace my approach rather than rushing to an abrupt stop; as the signals displayed a clearance interval ahead, I smoothly decelerated from 39 mph down to approximately 15–17 mph to time my arrival with the green arrow.
4. **Execution of Left Turn on Protected Green Arrow:** At 05:00:11 AM, as my vehicle reached the white left-turn arrow painted on the pavement, the dedicated overhead left-turn signal illuminated a Protected Green Arrow. Exactly as timed, I initiated my left turn smoothly on GREEN at approximately 15–17 mph without ever coming to a standstill in the turn lane.
5. **Alignment Facing North & Point of Inevitable Collision:** By 05:00:14 AM, I had fully cleared the intersection turn and my vehicle was aligned straight North (0.0° N) entering the entrance ramp. Looking through my right front passenger window toward Bass Pro Drive, I observed an oncoming white sedan (a 2014 BMW 550) traveling westbound past the Shell/Waffle House commercial driveway at high speed (approximately 40–45 mph) crossing the stop line without slowing. My vehicle was already broadside in the intersection with concrete curbs and medians ahead; there was no room to reverse and nowhere to steer.

6. **Broadside Collision & Total Impact:** At 05:00:15 AM, the adverse BMW ran the red light and slammed its front bumper directly into the right middle/rear side of my Atlas (3 O'Clock impact). My front bumper and front end sustained zero contact damage.
7. **Loss of Consciousness & Automated Emergency Dispatch:** The violent broadside impact knocked me unconscious and deployed all cabin airbags. The steering-wheel airbag ruptured, causing chemical burns across my chest. Because I was unconscious and non-responsive, Apple Crash Detection placed an automated emergency 911 call at 05:02 AM broadcasting that the owner was in a severe crash and unresponsive.
8. **On-Scene Police Statement:** When speaking to the investigating Grapevine police officer at the scene—which is preserved on video—I explicitly told the officer that my light was GREEN. I never stated, agreed, or suggested that I turned on a flashing yellow light. The officer's written narrative claiming I turned on a flashing yellow light is completely false and contradicted by my recorded words at the scene.
9. **Adverse Driver Status:** Adverse driver Tamika Savala-Fitzpatrick was driving without motor vehicle insurance, as confirmed on page 2 of the certified police crash report."

7. Formal Rebuttal to Officer Smith's Flawed Police Narrative

In the certified Texas Peace Officer's Crash Report (CR-4 Page 2), Officer R. Smith entered the following narrative:

"Unit 1 Failed to yield right of way while turning left on a flashing yellow light. Unit 1 entered the intersection striking unit 2 causing damage to both vehicles."

This narrative is **factually, physically, and electronically refuted** by five independent evidentiary pillars:

Pillar 1: On-Scene Recorded Video Audio Refutes "Flashing Yellow"

- Recorded video taken at the scene captures the client explicitly stating to the investigating officer that her light **WAS GREEN**.
- The client never stated, agreed, or suggested that she turned on a flashing yellow arrow. Officer Smith's narrative is an unsubstantiated insertion contradicted by contemporaneous recorded video audio.

Pillar 2: Certified Physical Damage Vectors Disprove "Unit 1 Struck Unit 2"

- **Unit 1 (Client Atlas):** Sustained damage exclusively at **3 O'CLOCK** (Right front quarter/side angular impact). **Front bumper was 100% undamaged.**
- **Unit 2 (Adverse BMW 550):** Sustained damage at **12 O'CLOCK** (Direct front-end distributed impact).
- **Physical Law:** It is a physical impossibility for Unit 1 to have "struck" Unit 2 when Unit 1's front bumper has zero contact damage and Unit 2's front nose crushed Unit 1's side doors. Unit 2 struck Unit 1 broadside.

Pillar 3: TxDOT Diamond Interchange Standards Require Protected Green Phase

- The intersection of Bass Pro Dr and SH 121 operates under Texas Department of Transportation (TxDOT) coordinated diamond interchange logic (TTI 4-phase standards).
- **Malfunction Management Unit (MMU) Hardware Interlock:** The NEMA TS2 traffic cabinet governing this diamond interchange contains a physical Malfunction Management Unit (MMU). The MMU continuously monitors electrical line voltages to the signal heads. It is physically and electronically impossible for the controller to illuminate a green turn arrow for eastbound traffic while simultaneously displaying green or yellow to opposing through traffic. Any detected voltage conflict instantly trips the cabinet into an emergency 4-way flashing red mode. This hardware fact conclusively proves the opposing driver ran a solid red light.
- Traffic released from the West ramp terminal on green is programmed with an internal bridge progression clearance offset. To prevent interior bridge gridlock, the master controller **must clear arriving bridge traffic by serving a Protected Green Arrow**, while simultaneously holding opposing through traffic (Unit 2 BMW) in **SOLID RED**.

Pillar 4: Sub-Second GPS Telematics Confirms Paced Green Turn & North Alignment

- The 13,285-record telematics dataset proves that the client decelerated smoothly to ~15–17 MPH on approach, reached the painted pavement arrow at 05:00:11 AM as the green arrow illuminated, and completed the turn at 05:00:14 AM facing **0.0° Straight North** inside the entrance ramp before the BMW crossed the stop bar.

Pillar 5: Adverse Driver Uninsured Status & Speeding Admission

- Adverse driver Tamika Savala-Fitzpatrick was operating an uninsured vehicle (Proof of Financial Responsibility: N0).

- She admitted to police that she saw the yellow light and accelerated to beat it, entering the intersection after opposing clearance had expired and the signal had turned solid red.

8. Traffic Signal Engineering, NEMA TS2 Controller Logs & Video Spoliation Protocol

To verify traffic signal timings, confirm the interconnected diamond controller logic, and secure all historical camera footage for the intersection of SH-121 and Bass Pro Drive / W. Bethel Road, counsel must immediately execute formal requests with both the **Texas Department of Transportation (TxDOT)** and the **City of Grapevine**.

Because traffic management on state highway frontage roads frequently involves state ownership coupled with municipal maintenance agreements, querying both entities simultaneously is the mandatory strategy to prevent evidence from being overwritten or lost.

8.1 Traffic Signal Timings & Controller Logs (NEMA TS2 Event Logs)

Collision liability relies on the NEMA TS2 controller logic proving that a protected green left-turn arrow for the eastbound approach strictly enforces a solid red light for opposing westbound traffic (adverse BMW).

1. TxDOT Fort Worth District (Primary Jurisdiction):

- **Corridor Contact:** Michael Peters (michael.peters@txdot.gov / 817-370-6846) is the documented TxDOT contact for the SH-121 corridor in Grapevine. He is the direct starting point to verify specific phase configurations and hardware in use at this diamond interchange.
- **Formal Open Records Request (ORR):** TxDOT requires a formal Open Records Request for signal timing logs. Counsel should submit written requests via email to TxDOT_ORR@txdot.gov or through the TxDOT Open Records Management and Tracking System.

2. City of Grapevine Public Works (Secondary Verification / Maintenance Agreement):

- **Facility:** Grapevine Municipal Service Center, 501 Shady Brook Dr, Grapevine, TX 76051.
- **Phone:** (817) 410-3330 (Public Works Direct) or (817) 410-3000 (City Main Line).

3. Specific Evidentiary Records Counsel Must Request:

- **"Phase Sequence and Ring-and-Barrier Diagrams"** for the SH-121 & Bass Pro Dr diamond interchange governing August 28, 2026.
- **"NEMA Event and Fault Logs"** for the master controller cabinet covering the window of **04:58 AM through 05:05 AM** on August 28, 2026.

8.2 Intersection & Corridor Video Surveillance Cameras

Counsel must distinguish between cameras that record historical footage and cameras that function purely as real-time vehicle sensors:

1. TxDOT Intelligent Transportation System (ITS) Monitoring Cameras (URGENT SUBPOENA):

- TxDOT operates an active regional ITS camera network in the DFW metroplex. The Fort Worth District system lists an active camera at this exact interchange labeled **"SH121 @ Bass Pro" (SH121.Bass Pro.SB)**.
- **Immediate Action Required:** Send a certified spoliation letter and subpoena immediately to the TxDOT Fort Worth District Traffic Management Center (TMC). TxDOT ITS cameras are utilized for active traffic management; footage is routinely overwritten within **72 hours to 7 days** unless a formal preservation hold is served.

2. Mast-Arm Traffic Light Cameras (Vehicle Detection Sensors — Non-Recording):

- Small camera units mounted directly to the signal mast-arms pointing down at travel lanes are Video Vehicle Detection Systems (VVDS / Iteris / Flir).
- **Function:** These optical sensors replace in-pavement induction loops to detect vehicle presence and call green phases.
- **Evidentiary Note:** These sensors process real-time pixel shifts and **do not record or store historical video**. Counsel can confirm hardware specifications with TxDOT or Grapevine Public Works, but should not rely on them for impact footage.

8.3 Third-Party Commercial Surveillance Spoliation Matrix

Certified spoliation letters demanding the preservation of all external exterior surveillance footage from **04:50 AM to 05:15 AM on August 28, 2026** must be sent immediately to adjacent commercial properties.

(Note: Counsel's paralegal should call each location to confirm the name of the current General Manager prior to mailing certified letters).

Entity / Property	Physical Address	Telephone	Surveillance Relevance
Shell Gas Station	2000 W Bethel Rd, Grapevine, TX 76051	(817) 421-2295	Immediate corner of Bass Pro Dr & W Bethel Rd; exterior pumps and canopy cameras face the intersection and adverse BMW westbound approach path.
Hampton Inn & Suites DFW North	1750 N Hwy 121, Grapevine, TX 76051	(972) 471-5000	Located directly adjacent to the SH-121 / Bass Pro interchange; parking lot and entrance cameras overlook frontage road corridor.
Aloft Dallas DFW Airport Grapevine	1033 N Main St, Grapevine, TX 76051 (<i>Physical mailing address</i>)	(817) 488-6677	Client's accepted Uber passenger pickup destination; exterior cameras document arrival approach and ambient lighting conditions.

9. Medical Evaluation, Diagnoses & Clinical Evidence Strategy

9.1 Acute Diagnoses at Baylor Scott & White (08/28/2026)

1. **Closed Head Injury / Concussion** (ICD-10 S06.0X0A).
2. **Cervical Spine Sprain / Whiplash** (ICD-10 S13.4XXA).
3. **Contusions / Hematomas:** Left clavicle, left upper anterior chest, right knee, left knee, lower extremities.
4. **Airbag Rupture Chemical Irritation:** Chemical chest burn from ruptured driver steering-wheel airbag.

9.2 Objective Diagnostic Workup Summary

- **CT Head (without contrast):** Normal (rules out acute intracranial hemorrhage; does not rule out concussion).
- **CT Cervical Spine:** No acute fracture; notes pre-existing hypertrophic changes (cervical spondylosis).
- **CT Chest, Abdomen & Pelvis (with contrast):** No acute traumatic internal hemorrhage or organ rupture.
- **CT Thoracic & Lumbar Spine:** Mild left foraminal stenosis at L3-L4; moderate left foraminal stenosis at L4-L5; left facet arthrosis at L5-S1.
- **Bilateral Knee Radiographs:** Right knee (07:35:56) and Left knee (07:42:09) negative for acute fracture (does not rule out meniscal, ligamentous, or chondral soft-tissue tears).

9.3 Corrections to Initial Hospital Charting & Corroborating Evidence

A. Rebuttal of "Pt Denies LOC" (Loss of Consciousness)

The ER chart carries a templated review-of-systems string stating "*Pt denies LOC.*" This is an inaccurate default entry contradicted by objective machine data:

- **Apple Crash Detection Automated Call (05:02 AM):** The client's iPhone detected a severe collision and initiated an emergency 911 broadcast specifically because **the client was non-responsive**. The automated audio broadcast stated: "*The owner of this iPhone was in a severe car crash and is not responding to their phone.*"
- **On-Scene Physical Incapacity:** Chart documents client was "**not ambulatory at scene**" and was immobilized in a cervical collar by Grapevine EMS.
- **Contemporaneous Dashcam Audio (05:04 AM):** Captures client altered, disoriented, and groggy immediately following airbag deployment.
- *Action:* Formal HIPAA amendment request submitted to Baylor Medical Records to correct the templated ROS string.

B. Emergence of Objective Seat Belt Sign & Extensive Ecchymosis

- The initial ER exam at 07:00 AM noted "*No bruising (no seat belt sign) noted.*" This was an accurate early observation, as traumatic ecchymosis requires 24–48 hours to surface.
- By 08/29, a textbook linear **seat belt sign ecchymosis** appeared across the client's left lower neck and left clavicle, matching the exact sites of tenderness documented on 8/28.
- Extensive ecchymosis also emerged across the upper torso, left knee, and shins, providing objective physical proof of severe restraint loading.

C. Emergence of Lower Leg Allodynia (Urgent Clinical Evaluation Required)

- Post-crash, client developed severe burning pain to light touch (**allodynia**) in the right lower leg with no visible contusion.

- Differential diagnosis: (1) Post-traumatic spread of Complex Regional Pain Syndrome (CRPS) triggered by severe blunt trauma; (2) Peripheral nerve contusion (superficial peroneal/saphenous nerve); (3) Deep vascular injury/thrombosis (noting ER pulse 101 and SpO2 drift from 95% to 93%).
- Requires immediate clinical documentation by PCP Dr. Uddin and pain specialist.

D. Missing Cervical Vascular Imaging

- The client underwent a prior **CTA Head/Neck on 08/17/2023** (Texas Health Plano) documenting baseline vascular anatomy (stenosis at brachiocephalic and left common carotid origins; tortuosity of left internal carotid; diminutive left vertebral artery).
- Given the blunt neck trauma, visible seat belt sign across the left carotid sheath, and head injury, contrast vascular imaging (CTA or MRA) is clinically warranted to rule out traumatic cervical arterial dissection, using the 2023 CTA as a direct comparison film.

E. Prescription & Anaphylaxis Safety Protocols

- **Anaphylaxis Warning:** Client is severely anaphylactic to Acetaminophen (APAP). Confirm pharmacy dispensed plain **Ultram (tramadol alone)** and NOT Ultracet (tramadol + acetaminophen).
- **Toradol (Ketorolac) Time Limit:** Potent NSAID limited to a strict 5-day maximum course.
- **Commercial Driving Restriction:** Tramadol (opioid) and Robaxin (muscle relaxant) severely impair cognitive function; client cannot drive commercially while prescribed these medications.

10. Pre-Crash Functional Baseline & Eggshell Plaintiff Doctrine

10.1 Long-Term CRPS Stability (Left Hand Only)

- **Origin Records (Rush Pain Center, Chicago, 2015-2016):** Formally coded ICD-10 G90.512 (*CRPS Type I of left upper limb*). Following a series of six stellate ganglion blocks in 2016, symptoms stabilized completely.
- **Anatomical Localization:** For over ten years, symptoms remained strictly localized to the dorsal left middle finger, side of ring finger, and thumb. **It was stable for years and never spread.**
- **Right Leg Allodynia is a NEW Injury:** The new right lower leg symptoms are in an anatomically distinct limb, representing a new traumatic injury rather than pre-existing CRPS.

10.2 Prior Cervical Spine MRI (Texas Health Frisco, 12/12/2024)

- A pre-crash cervical MRI performed 20 months prior showed multilevel disc desiccation, moderate C5-C6 height loss, and multilevel neural foraminal stenosis (severe left at C5-C7).

10.3 Unimpeachable Functional Baseline: 50,000+ Miles and ~2,000 Uber Trips

Insurers routinely attempt to minimize crash injuries by attributing symptoms to pre-existing CRPS or degenerative disc disease. **This defense is legally and factually impossible here:**

- Client logged **over 50,000 commercial rideshare miles and nearly 2,000 completed trips for Uber alone** in this vehicle prior to August 28, 2026.
- Operating full-time as a commercial driver with both hands on the wheel across tens of thousands of miles establishes that the client was **100% physically active, asymptomatic, and operating at full functional capacity.**
- Under the Texas **Eggshell-Plaintiff Rule**, a tortfeasor takes the victim as found; any traumatic aggravation of a pre-existing, asymptomatic condition is 100% compensable under Texas law.

11. Prior Repair History & Segregation of Damage (No Pre-Existing Right-Side Damage)

To prevent an insurance adjuster from improperly depreciating the total loss settlement by asserting "unrelated prior damage," client's complete certified repair history is fully documented:

Claim Date / Event	Claim Number & Carrier	Repair Facility	Point of Impact	Damage Segregation & Status
01/26/2026 (Personal)	Progressive #26-647168303-01 (Adj: Chrysanta Creque-Connors)	The Body Shop #2 - Prosper (430 Business Park Dr, Prosper, TX)	Left Side (9)	100% Repaired to OEM Standards. Odometer: 47,044 mi. Strictly limited to left driver-side panels.

Claim Date / Event	Claim Number & Carrier	Repair Facility	Point of Impact	Damage Segregation & Status
07/23/2026 (Commercial)	United Financial / Progressive #26-711114628-01 (Adj: Carly P)	Hendrick Volkswagen Frisco (5010 State Hwy 121, Frisco, TX)	Left Front Corner (11)	100% Repaired to OEM Standards. Inspected & reconditioned by certified VW dealership on 08/24/2026.
08/28/2026 (Current Collision)	Progressive #26-854858569 (Adj: Sloane S)	Euless B&B Wrecker Service (Storage)	RIGHT SIDE (3 O'CLOCK)	100% NEW DAMAGE FROM AUGUST 28 COLLISION. Total loss caused by adverse BMW broadside impact into right doors and B-pillar. Zero overlap with prior left-side claims.

Evidentiary Takeaway: Both prior claims involved the **LEFT** side of the vehicle and were fully repaired by certified body shops. The August 28 collision involves exclusively the **RIGHT** side (3 O'Clock) and interior cabin airbag deployments. Progressive cannot take any deduction for prior damage.

12. Property Damage, Total Loss Valuation & Storage Mitigation

12.1 Capital One Loan Payoff & Three-Band ACV Equity Strategy

- **Capital One 10-Day Payoff: \$39,688.03** (Good through September 8, 2026; Per Diem: \$13.82 — *Attorney Note: Obtain updated payoff statement at final settlement*).
- **Progressive Loan/Lease Payoff Coverage:** Covers up to **25% of Actual Cash Value (ACV)** with a **\$0 deductible**.
- **The Three ACV Strategic Bands:**
 1. **Band 1 (Below \$31,830.00):** Gap coverage caps at 25%; shortfall would exist. (Legally recoverable against adverse tortfeasor).
 2. **Band 2 (\$31,830.00 to \$39,787.03):** Loan is satisfied 100% with \$0 out-of-pocket debt, but client receives \$0 net equity.
 3. **Band 3 (Above \$39,787.03):** Every additional dollar negotiated is **100% NET CASH EQUITY IN CLIENT'S POCKET** for a down payment on a replacement vehicle.
- **Mandatory Texas 6.25% Sales Tax & Title/Registration Transfer Fees:** Under Texas Administrative Code (28 TAC § 5.401) and standard Texas insurance regulations, when a carrier totals a vehicle, the insurer **must pay the applicable 6.25% Texas motor vehicle sales tax** plus county title and registration transfer fees on top of the base ACV. On a \$35,000–\$40,000 valuation, this statutory mandate adds **+\$2,187.50 to +\$2,500.00 in mandatory compensation** that directly boosts net equity.

12.2 Critical ACV Adjustments & Equipment Hardening (Demands to Progressive)

1. **Four-Day Pre-Crash Reconditioning Credit (Hendrick VW Frisco, 08/24/2026):**
 - Just 96 hours before the crash (at ~58,800 miles), the Atlas underwent comprehensive mechanical reconditioning at Hendrick Volkswagen Frisco: brand-new tires, new brake pads, new brake rotors, suspension alignment, and certified multi-point inspection.
 - Under standard insurance total loss guidelines (CCC ONE / Mitchell), documented pre-crash reconditioning warrants a **dollar-for-dollar positive condition adjustment**, adding \$1,500–\$2,500 to baseline ACV and substantially mitigating any high-mileage deductions.
2. **Factory Equipment & Trim Package (SE Base FWD Confirmed):**
 - Confirmed via Mitchell Cloud Estimating System (Mitchell Code: 912009): Factory **2025 Volkswagen Atlas SE 2.0T FWD** (Deep Black Pearl).
 - Factory options to enforce on CCC ONE comparable matrix: 18" alloy wheels, heated/ventilated front bucket seats, heated steering wheel, power driver seat with lumbar support, dual-zone automatic climate control, rain-sensing wipers, privacy glass, and 3-row seating.

12.3 Storage Yard Mitigation (Euless B&B Wrecker Service)

- **Location:** 1201 W Euless Blvd, Euless, TX 76040 · (817) 283-2121.
- **Statutory Rate Cap:** Regulated under TDLR (16 TAC § 85.722) with daily storage strictly capped at **\$22.85 per day**.
- **Mandatory Preservation Notice:** Progressive must be instructed in writing to transfer the vehicle to an insurance storage facility to stop fee accrual, but **strictly prohibited from releasing the vehicle to salvage** until:
 1. The **Airbag Control Module (EDR)** crash pulse data is imaged.

2. A certified Volkswagen dealer diagnostic scan of stored trouble codes (powertrain, Front Assist, Hill Hold, Emergency Assist) is completed.
-

13. First-Party Coverage Analysis & Texas UM Legal Framework

13.1 Progressive Policy #936659747 Structure

- **Bodily Injury Liability:** \$250,007 / \$500,007
- **Property Damage Liability:** \$100,007
- **Personal Injury Protection (PIP): \$10,003** (No-fault; covers 100% medical bills and 80% lost wages)
- **Uninsured / Underinsured Motorist (UM/UIM): \$250,007 / \$500,007** (Primary bodily injury recovery)
- **UM Property Damage:** \$100,007 (\$250 deductible)
- **Collision:** \$99 Deductible
- **Comprehensive:** \$99 Deductible
- **Loan/Lease Payoff:** 25% of ACV (\$0 deductible)
- **Rental Reimbursement:** \$60/day (30 days / \$1,800 max)
- **Ridesharing Endorsement:** Active (Ridesharing: Yes on declarations page)

13.2 Texas Uninsured Motorist Law (*Brainard & Irwin Framework*)

- Under *Brainard v. Trinity Universal Ins. Co.*, 216 S.W.3d 809 (Tex. 2006), a Texas UM carrier has no contractual duty to pay benefits until the insured establishes the legal liability of the uninsured driver and damages.
- Under *Allstate Insurance Co. v. Irwin*, 627 S.W.3d 263 (Tex. 2021), insureds may resolve UM liability and recover statutory attorney's fees through a Uniform Declaratory Judgment Act (UDJA) action.
- **Strategic Advantage:** Because the adverse driver is confirmed completely uninsured and the sub-second GPS telematics, physical damage vectors, and on-scene video definitively disprove the police officer's narrative, Progressive has zero legal basis to deny liability. Presenting this comprehensive dossier establishes liability pre-suit, maximizing settlement posture.

13.3 Uber Commercial TNC Policy (Texas HB 3520 / Ins. Code § 1954.053)

- At the moment of impact, the client was in **Period 2** (app on, trip accepted, en route to pickup; upfront fare \$12.07).
- Under Texas law, the TNC provides statutory commercial auto liability (\$1M) and contingent commercial UM/UIM coverage. A formal claim notice has been logged with Uber Incident Management.
- **Uber Commercial Dispatch & \$0.00 App UI Artifact Explained:** At the moment of impact (05:00:15 AM), client was actively navigating under an accepted Uber dispatch (Period 2) to pick up a rider at the **Aloft Dallas DFW Airport Grapevine (N. State Hwy 121)** for transport to **DFW International Airport** (Upfront fare: \$12.07). The rider canceled post-impact at 05:05:00 AM (4 minutes 45 seconds after collision). Under Uber's app architecture, when a rider cancels prior to pickup, the platform automatically wipes the intended destination from the receipt and populates both pickup and dropoff fields with the server cancellation timestamp and GPS coordinates, displaying a \$0.00 fare. This artifact conclusively confirms active Period 2 dispatch at the moment of collision.

13.4 Medical Financing & Lien Mitigation

- **Texas Hospital Lien (Tex. Prop. Code Ch. 55):** Baylor Scott & White may file a statutory hospital lien against third-party/UM settlement funds.
- **Charity Care / Financial Assistance:** As an uninsured patient, client is eligible for Baylor's nonprofit Financial Assistance Policy (FAP). Application must be requested prior to any settlement distribution.
- **Letters of Protection (LOP):** Specialized post-crash care (orthopedic knee MRI, neurology, pain management) should be secured through Letters of Protection to avoid exhausting PIP funds required for living expenses and lost wages.

14. Master Exhibit Index & Evidence Repository

All electronic files, forensic models, datasets, and certified documents are maintained in the client's evidence repository:

□ C:\Users\melod\OneDrive\AppData\Evidence\Folder_1_Interactive_Accident_Reconstruction

Exhibit	Title / Identifier	Description & Evidentiary Value
Exhibit 1	Certified Police Crash Report	TxDOT Crash ID 21609720.1 / Case 2600037671 (Certified 09/02/2026). Confirms Unit 2 was UNINSURED and documents 3 O'Clock vs 12 O'Clock damage vectors.
Exhibit 2	13,285-Record GPS Telematics	Sub-second dataset (gps_full_data.js). Proves 26s stop at West light, bridge crossing, amber deceleration to 17 MPH, green arrow trigger, and 0.0° North alignment.
Exhibit 3	Interactive Forensic Reconstruction	Web application (index.html). Models dual TxDOT diamond signal controller, vehicle kinematics, speed graph, and driver viewpoint.
Exhibit 4	On-Scene Video Audio	Recorded video taken at the scene where client explicitly states to police officer: <i>"My light was green."</i> Directly refutes officer's narrative.
Exhibit 5	Dashcam Exhibit A Photo	Hardware-stamped scene photo (05:05:43 AM) documenting severe structural intrusion, deployed side curtains, and chemical airbag residue.
Exhibit 6	Apple Crash Detection 911 Call	Automated 911 dispatch recording (05:02 AM) stating owner was in severe crash and unresponsive. Directly refutes "denies LOC" ER entry.
Exhibit 7	Physical Ground-Truth Imagery	Google Street View matching of the white pavement left-turn arrow (32.955021° N) and the driver northbound viewpoint at the point of inevitable impact (32.955075° N).
Exhibit 8	Hendrick VW Reconditioning Invoice	Repair Order & Multi-Point Inspection dated 08/24/2026 (58,765 miles). Establishes pristine mechanical condition 96 hours pre-crash for ACV credit.
Exhibit 9	Baylor ER Medical Records	Encounter 08/28/2026 (MRN 15608293, Dr. Holt). Diagnoses closed head injury, cervical sprain, and acute contusions.
Exhibit 10	Pre-Crash Cervical Baseline MRI	Texas Health Frisco MRI (12/12/2024). Documents pre-existing baseline cervical anatomy 20 months prior to collision.
Exhibit 11	Historical CRPS Treatment Records	Rush Pain Center (2015–2016). Documents long-term stability of left-hand CRPS following stellate ganglion blocks.
Exhibit 12	Commercial Driving History	Platform records establishing 50,000+ miles and ~2,000 trips for Uber alone, proving full functional physical capacity prior to crash.

15. Contemporaneous Logs

15.1 Daily Symptom & Functional Limitation Log

Date	Head / Cognitive	Neck / Cervical	Torso / Restraint	Extremities (Knees/Shins)	Right Leg Allodynia	Functional Limitations
08/28	Groggy, LOC at scene, severe headache	Severe neck stiffness, immobilized in C-collar	Chest burning from airbag chemical rupture	Bilateral knee pain, shin tenderness	Numbness / initial tingling	Non-ambulatory; ER transport
08/29	Persistent headache, light sensitivity	Muscle spasms, pain radiating to left shoulder	Visible seat belt sign ecchymosis on left neck/clavicle	Extensive bruising left knee and shins	Burning pain to light touch across right lower leg	Unable to drive; difficulty walking; bed rest
08/30	Drowsiness, cognitive fatigue	Restricted range of motion	Darkening purple bruising across torso	Swelling left knee, pain on weight-bearing	Severe burning with clothing contact	Unable to perform household tasks
08/31	Continued headache	Pain upon turning head	Tenderness over left sternum/ribs	Knee stiffness	Persistent allodynia; logging for clinical visit	Commercial driving strictly contraindicated

15.2 Expense & Lost Earnings Ledger

Date	Category	Payee / Description	Amount	Billed To / Source
08/28/2026	Emergency Medical	Baylor Scott & White ER Encounter (MRN 15608293)	\$13,528.55 balance due per MyBSWHealth portal (statement dated 09/01/2026; itemized statement not yet obtained)	Pending Charity Care / PIP
08/28/2026	Pharmacy	CVS #10523 (Toradol, Robaxin, Tramadol)	Out of Pocket	Submitted to PIP (\$10,003)
08/28/2026	Tow & Impound	Euless B&B Wrecker Service (Tow & Storage)	TBD (Statutory Cap \$22.85/day)	Progressive Collision / Subrogation
08/28-Pres.	Lost Earnings	Uber Commercial Driving (Baseline: ~2,000 trips / 50k mi)	Estimated ~\$1,200-\$1,500/week	PIP Wage Loss (80%) & UM Claim

16. Case Action Plan & Legal Roadmap

Immediate Priorities (Clinical & Claim Administration)

- ☐ **PCP Clinical Follow-Up (Dr. Sarah Uddin):**
 - Physical exam of **right lower leg allodynia** (burning pain to light touch, no bruise); evaluate CRPS spread vs peripheral nerve injury vs vascular etiology.
 - Document visible **seat belt sign ecchymosis** across left lower neck and clavicle matching 8/28 tenderness.
 - Compare cervical vasculature against 2023 CTA Head/Neck comparison study.
 - Issue formal **written commercial driving restriction** based on closed head injury and sedating prescriptions.
- ☐ **Pain Management Specialist Consultation:**
 - Establish clinical baseline confirming left-hand CRPS was stable for 10 years without spread prior to trauma.
 - Evaluate and initiate treatment for new post-traumatic right lower leg allodynia.
- ☐ **Progressive UM & Total Loss Administration (Adjuster Sloane S):**
 - Submit this Master Dossier formally placing Progressive on notice of an **Uninsured Motorist (UM)** bodily injury and property damage claim.
 - Confirm application of the personal \$99 collision deductible under the active rideshare endorsement.
 - Submit Capital One payoff letter (\$39,688.03) and demand Hendrick VW reconditioning condition adjustment on total loss valuation.
 - Demand preservation of vehicle EDR and execution of dealer diagnostic scan before salvage release.
- ☐ **Formal Legal Retainer:**
 - Retain experienced Texas personal injury counsel to formally file the Uninsured Motorist claim and enforce liability under *Allstate v. Irwin*.