
## www.EngineeringForLess.com

# 3 axis step motor controller with 5 general I/O's control

### babakmanafi@yahoo.com

Digital Inputs		Digital Outputs	
UNO pin #	Input #	UNO pin #	Output #
Pin 11	In 01	Pin 8	Out 01
Pin 12	In 02	Pin 9	Out 02
_	-	Pin 10	Out 03
_	-	_	-
_	-	_	-
_	-	_	-
_	-	_	-
_	-	_	-
_	-	_	_
_	-	_	-
_	-	_	-
_	-	_	_
_	_	_	-
_	_	_	-
_	_	_	-
_	-	_	-

#### Digital input or Ref. switch setup



#### Emergency shut down

