



Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	David Kiely - BSS Scaffolding	Signature:	
Site Address:	KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland	Location / Description of Scaffold:	54-59 3 lifts high
Date & Time of Inspection:	2025-08-18 10:59:48		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	None
Sole Boards	Sole boards rotten underneath jack	Sole boards replaced
Base plates & Base Jacks	Good	None
Standards	Good	None
Ledgers	Ledgers bent	Ledgers replaced
Transoms	Missing transoms	Replaced
Tie Spacing & Capacity	None	None
Anchorage test results	None	None
Facade bracing	Missing braces	Bracing replaced and put back in
Pian bracing	None	None
Cross bracing	None	None
Guard rails	None	None
Toe Boards	Toe boards missing	Replaced
Decking / scaffold boards	Wooden boards rotten	Boards replaced
Scaffolding signs and tags	Tags all in order	None
Loading in line with design / Manufacturer's instructions	All within manufacture design	None
Access / egress	Good	None

Item Inspected	Condition (Include any defected found)	Corrections taken / required
User behaviour / housekeeping	Area tidy	None
Unauthorised alterations	None	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electriaty)	None	None

Other outcomes of inspection / Observation: Everything updated and In working order