

Our Ref: qdos25043
Your Ref: JF/MR/34263/1

Date: 10/01/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Mr Jack Brownlee: 07/01/2025


In accordance with your instructions received on 09/01/2025 requesting us to provide an independent accident damage report, we assessed the damage on 10/01/2025. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	PORSCHE	Registration	ST24YVA
Model	911 CARRERA GTS S-A	Status	Repair
Category		Salvage Value	
Repair Cost	£12,634.25	Legal Status	Roadworthy
Engineer Value	£118,750.00	Impact Magnitude	Moderate



Impact Area





Our Ref: qdos25043

Your Ref: JF/MR/34263/1

Date: 10/01/2025

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the rear.

ENGINEER'S COMMENTS

Please note the valuation is based on average mileage.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £12,650.00 would be reasonable on this occasion.

REPAIR DURATION

We consider that this repair will take some 7 to 8 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.


Vehicle Data

Retail Value	£118,750.00
Trade Value	£107,750.00
Engineer's Value	£118,750.00
Glass's Code	
VIN	WP0ZZZ990RS217391
Odometer	
Engine	2981
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Rear Bumper Lining
Rear Bumper Spoiler
Left Rear Bumper Inner Side Distance-Sensor
Left R. Bumper Inner Distance-Sensor Bracket
Rear Bumper Lining Screw
B/Lid/Back Door/T/gate Type Designation
Left Exhaust Tailpipe

Rear Bumper Impact Absorber/Filler
Rear Bumper Repair Kit
Right Rear Bumper Inner Side Distance-Sensor
Right R. Bumper Inner Distance-Sensor Bracket
Rear bumper lining Nut
Boot Lid/Back Door/Tailgate Emblem
Right Exhaust Tailpipe



Our Ref: qdos25043

Your Ref: JF/MR/34263/1

Date: 10/01/2025


Additional operations

"A" Pillar NS paint
A Pillar OS Paint materials
Quarter Panel nearside paint materials
ADAS methods Research Fee
check exhaust / silencer
Energy cost supplement
Pre repair cleaning charge (including sa
Repair method research charge
Sundries
System Diagnostic Check (Pre Repair)
Wash/Clean
Paint Rear Body Cover, Complete
Paint Right Rear Bumper Distance-Sensor
Paint Colour mixing (1)


"A" Pillar OS paint
A Pillar NS Paint Materials
Quarter Panel Offside paint materials
Assessment Damage Appraisal Charge
check rear bumper reinforcer
Reset ADAS
QC & Road Test
Standard shutdown
System Diagnostic Check (Post Repair)
Vehicle Care Kit
Wheel Alignment (4 wheel)
Paint Left Rear Bumper Distance-Sensor
Paint Prep. synthetics (on vehicle without pre-painting)
Paint Sample colour creation (1)

Repair Cost Calculations

Hours	30.50
Hourly Rate	£99.00
Total Labour	£3,019.50
Parts	£5,473.95
Paint/Materials	£621.11
Specialist/Other	£1,413.98
Sub total	£10,528.54
Vat	£2,105.71
Total Estimated Cost	£12,634.25







Our Ref: qdos25043

Your Ref: JF/MR/34263/1

Date: 10/01/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: qdos25043

Your Ref: JF/MR/34263/1

Date: 10/01/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

ST24YVA.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos25043.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10