

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: CE000173
Version: vbr040ch/1

Full Report
Printed: 20/10/2023

Summary Information

Claim

Authorisation Status:	Interim	Date of Incident:	Not Known
Work Provider:	OTHER	Able to Authorise Repairs:	TBA
Claim Reference:		Repairs Authorised?	TBA
Policy Number:		VAT Portion Payable:	TBA
Other Reference:		Repairer:	
		Estimated Repair Time (Working Days):	

Vehicle Details

Vehicle

Manufacturer:	FORD
Model:	TRANSIT Trend
Model Sheet Number:	210
Engine:	2.0 LTR 95 KW
Registration Number:	LC71ODE
VIN Number:	WF0EXXTTREM65996
Registration Month:	November
Registration Year:	2021
Odometer:	25489 miles
Colour:	GREY
Paint Code:	PSTDK
Build Date:	FROM 08/2021
Selection Type:	AudaVIN+
Fuel Type:	Diesel
Vehicle Imported:	No

Model Specs

FROM 08/2021
AIR CONDITIONING
TINTED REAR WINDOWS
WINDSCREEN-HEATED
WINDSCREEN W/SENSOR
DOUBLE CENTRAL LOCK
GLOVEBOX WITH LOCK
ELEC/HEATED D/MIRROR
S-WHEEL RADIO CONT
NAVIGAT SYSTEM FORD
6 SPEAKER
FORD SYNC 3
FOG LAMPS
ADAPTIVE HEADLAMPS
FRONT LUMBAR SUPPORT
EMERGENCY CALL SYS
COMBI INSTR COL DISP
ANTI-THEFT ALARM
FRONT CAMERA
LED DOWNLIGHT
LEATHER S-WHEEL/KNOB
ULTRASONIC PARK SYS
MUDFLAP
ALTERNATOR 240A
EMISSION STD EURO6.2
2.0 LTR 95 KW
FORD EASY FUEL
6-SPEED
FRONT DRIVE
INTELLIGENT CRUISE
EMERGENCY BRAKE ASS
ELECT POWER STEERING
PASSENGER AIRBAG
TYRE PRESSURE SENSOR
TYRES 235/65 TR 16
WHEELS 6J X 16

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: CE000173
Version: vbr040ch/1

Full Report
Printed: 20/10/2023

WHEEL COVER 16 INCH
DOUBLE AERIAL
GWR 3500 KG
STOP-START SYSTEM
BLINDSPOT ASSIST
LANE CHANGING ASSIST
L/SLIDING DOOR
RR WING DOOR 270 DEG
HIGH ROOF
VAN WITH TRUCK REG
WHEELBASE 3750 MM
GRILLE SILVER/CHROME
BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering Rim Ply:
Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

Severity of Impact:
Vehicle Status on Inspection:
Date of Inspection: 20/10/2023



Tyres Condition:

Tread Depth LHF:
Tread Depth LHR:

Tread Depth RHF:
Tread Depth RHR:

Damage Areas:

Direction of Impact:



TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKES ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: CE000173
Version: vbr040ch/1

Full Report
Printed: 20/10/2023

Addresses

No addresses entered.

Cost Summary

Total Labour	£4,255.00
Total Paint/Material	£3,212.41
Total Parts	£4,863.37
Additional Costs	£700.50
Grand Total Exc VAT:	£13,031.28
20 % VAT:	£2,606.26
Grand Total Inc VAT:	£15,637.54
Excess:	TBA

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price = £50.00/HR

Repair / Guide

Number	Description	Work Units
NO NUMBER	ADD/TIME FOR ONE MAIN POSITION	2.0
44 030 4	RIGHT FRONT DOOR EDGE SEALANT	2.0
44 253 2	R + R RIGHT FRONT WING (FRT BUMPER AND R/HEADLAMP REMOVED) INCLUDES: R + R R/F WHOUSE SHELL	6.0
43 427 1	R + R FRONT BUMPER INCLUDES: BOTH HEADLAMPS, FRT MOULDINGS W-HOUSE R + R NOT INCLUDED: ADJUST HEADLAMPS.	8.0
44 263 3	R + R FRONT LOCK CARRIER (FRONT BUMPER REMOVED) NOT INCLUDED: ADD/WORK	10.0
42 115 1	R + R WINDSCREEN INCLUDES: R + R AIR GRILLE, WIPER ARMS AND NECESSARY TRIMS	16.0
33 903 5	ADJUST FRONT CAMERA	4.0
NO NUMBER	RENEW RIGHT CENTRE ROOF FRAME	79.0
NO NUMBER	R + R RIGHT SILL PANEL EXTENSION	1.0
NO NUMBER	RENEW RIGHT A-PILLAR ADD	120.0
NO NUMBER	R + R R/F SILL TRIM	1.0
44 413 4	RENEW R/DOOR (DOOR REMOVED) INCLUDES: CONVERT ATTACHED PARTS, RENEW IF NECESSARY	19.0
41 316 1	R + R RIGHT FRONT DOOR	2.0

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: CE000173
Version: vbr040ch/1

Full Report
Printed: 20/10/2023

41 356 1	R + R RIGHT FRONT STRIKER PIN	1.0
41 375 1	R + R R/F DOOR SEAL	2.0
41 336 8	DIS + ASS R/F DOOR LOCK CYLINDER	3.0
44 414 8ZAX	R + R R/UPPER A-PILLAR HINGE	1.0
44 414 8ZAX	R + R R/LOWER A-PILLAR HINGE	1.0
NO NUMBER	R + R R/R MOULDING FRONT	1.0
NO NUMBER	REMOVE AND REFIT R/R S-PANEL MOULDING	1.0
NO NUMBER	RENEW R/F SIDE PANEL	110.0
NO NUMBER	RENEW R/CENTRE INNER SIDE PANEL	57.0
NO NUMBER	R + R R/F STOP BUFFER	1.0
NO NUMBER	R + R R/R SIDE PANEL MOULDING	1.0
	INCLUDES: R/R WHEELHOUSE MOULDING	
	REMOVE AND REFIT	
43 447 1	R + R REAR BUMPER	2.0
43 614 1)	R + R RIGHT UPPER B-PILLAR TRIM	1.0
43 618 1	R + R RIGHT B-PILLAR TRIM	1.0
43 610 1)	R + R FRONT LOAD COMPART HEADLINING	12.0
29 099 1	READ AND DELETE ERROR MEMORY	1.0
	INCLUDES: DIAGNOSTIC UNIT CONNECTION.	
32 113 1	ADJUST HEADLAMPS	1.0
3742	REPAIR R/R LOWER SIDE PANEL	30.0*
1000	Repair Miracle Pull	10.0*
1000	Jig, Pull, Meas Jig, Pull & Measure	30.0*
1000	Identify ADAS reprogramming	5.0*
1000	Specialist Road test and QC	10.0*
1000	Corrosion Prote Corrosion Protection	5.0*
Total Work Units		557.0
Total Panel / Mechanical Labour		55.70 HRS
		£2,785.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = £50.00/HR

Repair /Guide	Description	
Number	BASECOAT CLEAR	Work Units
1482	RIGHT FRONT DOOR NEW PART PAINTING	21.0
2228	R/OUTER A-PILLAR NEW PART PAINTING	9.0
2362	R/CTR ROOF FRAME NEW PART PAINTING	25.0
2364	R/R ROOF FRAME NEW PART PAINTING	28.0
3482	R/F SIDE PANEL NEW PART PAINTING	101.0
4110	R/CTR INN SIDE PANELSURFACE PAINT	5.0
742	R/F WING REPAIR PAINTING <50%	11.0
2353	REAR ROOF SURFACE PAINT	22.0
2396	R/ROOF SKIN EXTENS SURFACE PAINT	5.0
3512	R/R SIDE PANEL SURFACE PAINT	20.0

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: CE000173
Version: vbr040ch/1

Full Report
Printed: 20/10/2023

1000	Denib Specialist	24.0*
	PREPARATION FOR PRE-PAINTING	23.0
Total Work Units		294.0
Total Paintwork Labour		29.4 HRS. £1,470.00

MATERIAL COST - PAINT

COST

Total Paint Cost	£3,468.92
Sundry Paint Material	£100.43
Pre-Painting Sundry Materials	£0.00
Total Excluding Pearlescent Uplift	£3,212.41
Pearlescent Uplift @ 0.0%	£0.00
Discounted by 10%	-£356.94
Total Paint And Material Cost	£3,212.41

PARTS

Price Valid: 02/10/2023

Guide No.	Description	Part Number	Bet.	Price
750	R/SCREW	5 237 591	0%	£2.84
752	R/NUT	1 766 938	0%	£8.96
782	R/F WING TRIM	2 016 818	0%	£25.03
884	R/F W-HOUSE MLDG FRT	2 365 746	0%	£35.84
886	R/F W-HOUSE MLDG RR	2 309 282	0%	£19.24
1411	WINDSCREEN BOND KIT	2 053 958	0%	£36.91
1412	FRONT SCREEN SEALANT	1 935 159	0%	£16.71
1482	RIGHT FRONT DOOR		0%	£750.00 *
1488	R/F UPPER DOOR HINGE	2 022 343	0%	£46.37
1496	R/F LOWER DOOR HINGE	2 415 776	0%	£46.37
1506	R/F DOOR CHECK	2 598 269	0%	£43.29
1510	R/F DOOR SEAL	2 622 094	0%	£73.73
1516	R/F LOWER DOOR SEAL	2 367 641	0%	£19.13
1528	R/F DOOR FRONT SEAL	2 011 013	0%	£13.21
1548	R/F WINDOW REGULATOR		0%	£160.00 *
1566	R/F DOOR OUT HANDLE	1 691 718	0%	£15.56
1569	DR/DOOR LOCK CYL	2 363 744	0%	£58.80
1578	R/F DOOR LOCK	2 425 730	0%	£205.28
1582	R/F STRIKER	1 515 243	0%	£19.91
1682	R/F DOOR MOULDING	2 309 266	0%	£50.27
1714	R/INN DOOR TRIM FOIL	1 868 788	0%	£59.41
2096	R/OUTER A-PILLAR	1 829 175	0%	£569.00

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: CE000173
Version: vbr040ch/1

Full Report
Printed: 20/10/2023

2206	R/F SILL EXTENSION	2 309 400	0%	£48.76
2362	R/CTR ROOF FRAME	1 862 204	0%	£145.23
2594	R/R S-PANEL MOULDING	2 402 558	0%	£62.77
3482	R/F SIDE PANEL	1 874 713	0%	£1,335.00
3614	R/CTR S/PANEL MLDG	2 309 370	0%	£107.57
3616	R/R S-PANEL MOULDING	2 309 304	0%	£31.79
3672	R/R WHEELARCH TRIM	2 309 382	0%	£82.08
4110	R/CTR INN SIDE PANEL	2 523 518	0%	£633.00
4862	R/F SILL PANEL COVER	2 474 610	0%	£47.03
Sub Total				£4,769.09
Deduction from RRP (0.0 %)				£0.00
Sundry Parts (2 %)				£94.28
Total Parts				£4,863.37

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras				
	Description		Betterment	Price
	WHEEL ALIGNMENT	Specialist	0%	£100.00
	OSF TYRE	osf tyre	0%	£100.00
	Side decals	Supply and fit	0%	£100.00
	Energy cost supp	Specialist	0%	£50.00
	Envirnomenta Charge	Specialist	0%	£25.00
	Estimate Charge	Specialist	0%	£50.00
	METHODS RESEARCH	Specialist	0%	£40.00
	Pre Sweep	Specialist	0%	£50.00
	Post sweep	Specialist	0%	£50.00
	PPE Equipment	Specialist	0%	£12.50
	Sanitsing of vehicle	Specialist	0%	£40.00
	Vehicle Care Kit	Specialist	0%	£8.00
	Body Filler	Specialist	0%	£10.00
	Boron drill bit	Specialist	0%	£43.00
Total Extras				£678.50

Calculation

20/10/2023

Labour			
	Total Panel/Mechanical	£2,785.00	
	Total Paintwork	£1,470.00	
Total Labour			£4,255.00
Total Paint/Material Costs			£3,212.41
Total Parts			£4,863.37

TEL: COLLISION ENGINEERS
01515590762 77-79 HOYLAKE ROAD
MORETON
WIRRAL, CH46 9PY

Assessment Number: CE000173
Version: vbr040ch/1

Full Report
Printed: 20/10/2023

Additional Costs

Corrosion Protection Materials External	£22.00
Cost of Specialist	£678.50

Total Additional Costs

£700.50

Grand Total Excl VAT

£13,031.28

VAT @ 20 %

£2,606.26

Grand Total Incl VAT

£15,637.54

Excess

TBA

Assessment Notes

No assessment notes entered.