

Summary Information

Claim

Authorisation Status:	Interim	Date of Incident:	Not Known
Work Provider:	Qdos	Able to Authorise Repairs:	TBA
Claim Reference:	EMS/11916/1	Repairs Authorised?	TBA
Policy Number:		VAT Portion Payable:	NonTaxable
Other Reference:		Repairer:	
		Estimated Repair Time (Working Days):	

Vehicle Details

Vehicle

Manufacturer:	VOLKSWAGEN
Model:	POLO Moda
Model Sheet Number:	6P6
Engine:	1.2 LTR 44 KW
Registration Number:	LP11EBX
VIN Number:	WVWZZZ6RZCY504799
Registration Month:	July
Registration Year:	2011
Odometer:	95573 miles
Colour:	GREY
Paint Code:	Not Known
Build Date:	FROM 03/2011
Selection Type:	

Model Specs

FROM 03/2011
1.2 LTR 44 KW
3-DOOR
TWO COAT METALLIC
PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	Medium
Steering Rim Ply:	Vehicle Status on Inspection:	Mobile
		Roadworthy
Brakes Pedal Travel:	Date of Inspection:	31/03/2022
Place of Inspection:		
Pre-Accident Damage:		



Tyres Condition:

Tread Depth LHF:
Tread Depth LHR:

Tread Depth RHF:
Tread Depth RHR:

Damage Areas:

Direction of Impact:



CITYGATE GROUP BODYSHOPS**TEL: 020 8842 7700****Assessment Number: RL000061****Version: vbr023hp/1****Full Report****Printed: 06/06/2022****Addresses****Assessor**

Rich Lailey
 Business Tel : 01494 842611
 Email Address :
 richard.lailey@citygate.co.uk

Insured

REBECCA MEALYER

Repairer

Citygate Bodyshop Wooburn
 Wooburn Green
 Bucks
 Mobile Tel : 07444 835952

Cost Summary

Total Labour	£290.00
Total Paint/Material	£407.96
Total Parts	£426.23
Additional Costs	£123.50
Grand Total Exc VAT:	£1,247.69
20 % VAT:	£249.54
Grand Total Inc VAT:	£1,497.23
Excess:	£0.00

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price = £50.00/HR****Repair / Guide**

Number	Description	Work Units
66 76 19 50	R + R L/R WHEELHOUSE SHELL (WHEEL REMOVED)	2.0
66 76 19 50	R + R R/R WHEELHOUSE SHELL (WHEEL REMOVED)	2.0
70 39 19 00	R + R REAR LOCK CARRIER COVER	2.0
94 31 20 00	R + R BOTH TAIL LAMPS	3.0
63 69 19 50	R + R REAR BUMPER COVER (TAILLAMPS REMOVED)	3.0
63 69 55 50	RENEW REAR BUMPER COVER (REMOVED)	2.0
	INCLUDES: R + R NUMBER PLATE LAMPS AND NUMBER PLATE	
53 82 19 50	R + R REAR CROSSMEMBER (BUMPER COVER REMOVED)	2.0
44 05 19 00	R + R REAR WHEEL (WHEELS)	2.0
1000	CHECK FINAL INSPECTION	5.0*
1000	DETAIL AND CLEAN CAR	5.0*
Total Work Units		28.0
Total Panel / Mechanical Labour		2.80 HRS
		£140.00

CITYGATE GROUP BODYSHOPS

TEL: 020 8842 7700

Assessment Number: RL000061

Version: vbr023hp/1

Full Report

Printed: 06/06/2022

PAINT WORK

Time Basis 10 WU = 1 HR. Price = £50.00/HR

Repair /Guide	Description	Work Units
Number		
2583	REAR COVER BUMPER NEW PART PAINT K1R	13.0
	PREPARATION FOR PRE-PAINTING	17.0
Total Work Units		30.0
Total Paintwork Labour		3.0 HRS.
		£150.00

MATERIAL COST - PAINT

COST

Total Paint Cost	£336.09
Sundry Paint Material	£0.00
Pre-Painting Sundry Materials	£117.20
Total Excluding Pearlescent Uplift	£336.09
Pearlescent Uplift @ 0.0%	£0.00
Discounted by 10%	-£45.33
Total Paint And Material Cost	£407.96

PARTS

Price Valid: 09/05/2022

Guide No.	Description	Part Number	Bet.	Held Date	Price
2583	REAR BUMPER	6R6 807 421 BH GRU	0%		£271.25
2617	L/R BUMPER GUIDE	6R6 807 393 A	0%		£18.84
2618	R/R BUMPER GUIDE	6R6 807 394 A	0%		£18.84
2640	REAR BUMPER SUPPORT	6R0 807 305 A	0%		£104.56
2702	REAR NUMBER PLATE	KNPL6	0%		£0.00
3361	L/NUMBER PLATE LAMP	1K8 943 021	0%		£14.27
3362	R/NUMBER PLATE LAMP	1K8 943 021	0%		£14.27
Sub Total					£442.03
Deduction from RRP					(5 %) -£22.10
Sundry Parts					(1.5 %) £6.30
Total Parts					£426.23

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

CITYGATE GROUP BODYSHOPS**TEL: 020 8842 7700****Assessment Number: RL000061****Full Report****Version: vbr023hp/1****Printed: 06/06/2022****Extras**

Description		Betterment	Price
PRE/POST SWEEP	MANUFACTURE APP	0%	£90.00
EPA CHARGE	Specialist	0%	£8.50
RESEARCH	TECH DATA	0%	£25.00
Total Extras			£123.50

Calculation**06/06/2022****Labour**

Total Panel/Mechanical	£140.00
Total Paintwork	£150.00

Total Labour **£290.00****Total Paint/Material Costs** **£407.96****Total Parts** **£426.23****Additional Costs**

Cost of Specialist	£123.50
--------------------	----------------

Total Additional Costs **£123.50****Grand Total Excl VAT** **£1,247.69**

VAT @ 20 %	£249.54
------------	----------------

Grand Total Incl VAT **£1,497.23**

Excess	£0.00
--------	--------------

Assessment Notes

No assessment notes entered.