

Assessment Number: GW035469
Version: VBRA62M/1

Summary Report
Printed: 11/08/2021

Summary Information

Claim

Insured:	M Abbass Amjad	Repairer:	
Insurer:		Engineer:	
Claim Reference:		Policy Number:	

Vehicle Details

Manufacturer:	VOLKSWAGEN	Registration Month:	October
Model:	PASSAT SE	Registration Year:	2011
Model Sheet Number:	6C2	Odometer:	Not Known
Engine:	2.0 LTR 103 KW	Colour:	GREY
		Paint Code:	I7F
Registration Number:	BJ61YVT	VIN Number:	WVWZZZ3CZCE085328
Build Date:	FROM 05/2011		
Selection Type:	AudaVIN+		

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price = £55.00/HR

Repair / Guide

Number	Description	Work Units
44 05 19 00	R + R REAR WHEEL (WHEELS)	2.0
66 76 19 50	R + R L/R WHEELHOUSE SHELL	2.0
	(WHEEL REMOVED)	
66 76 19 50	R + R R/R WHEELHOUSE SHELL	2.0
	(WHEEL REMOVED)	
94 31 55 50	RENEW L/TAILLAMP (REMOVED)	1.0
94 31 55 50	RENEW R/TAILLAMP (REMOVED)	1.0
94 31 20 00	R + R BOTH TAIL LAMPS	2.0
53 82 19 50	R + R REAR CROSSMEMBER	2.0
	(BUMPER COVER REMOVED)	
63 69 19 50	R + R REAR BUMPER COVER	4.0
	(TAILLAMPS REMOVED)	
63 69 55 50	RENEW REAR BUMPER COVER	7.0
	(REMOVED)	
	INCLUDES: R + R MOULDINGS AND LOWER SPOILER	
2711	CHECK REAR PANEL	
1000	CHECK AND QUALITY CONTROL	5.0*
1000	CHECK AND CLEAN CAR	5.0*
Total Work Units		33.0
Total Panel / Mechanical Labour		3.30 HRS
		£181.50

Assessment Number: GW035469
Version: VBRA62M/1

Summary Report
Printed: 11/08/2021

PAINT WORK

Time Basis 10 WU = 1 HR. Price = £55.00/HR

Repair /Guide	Description	Work Units
Number		
2583	REAR COVER BUMPER NEW PART PAINT K1R	13.0
2607	REAR COVER NEW PART PAINT K1R	3.0
1000	MACHINE POLISH	5.0*
	PREPARATION FOR PRE-PAINTING	17.0
Total Work Units		38.0
Total Paintwork Labour		3.8 HRS. £209.00

MATERIAL COST - PAINT

COST

Total Paint Cost	£328.17
Sundry Paint Material	£0.00
Pre-Painting Sundry Materials	£109.30
Total Excluding Pearlescent Uplift	£437.47
Pearlescent Uplift @ 0.0%	£0.00
Total Paint And Material Cost	£437.47

PARTS

Price Valid: 01/07/2021

Guide No.	Description	Part Number	Bet.	Held Date	Price
2583	REAR BUMPER	3AE 807 417 F GRU	0%		£403.45
2605	REAR BUMPER SPOILER	3AE 807 521 A 9B9	0%		£116.10
2607	REAR COVER	3AE 807 441 A GRU	0%		£7.81
2613	L/R BUMPER MOULDING	3AE 807 459 2ZZ	0%		£48.70
2614	R/R BUMPER MOULDING	3AE 807 460 2ZZ	0%		£48.70
2617	L/R OUT BUMPER GUIDE	3AE 807 393 A	0%		£11.59
2618	R/R OUT BUMPER GUIDE	3AE 807 394 A	0%		£11.59
2619	L/R BUMPER GUIDE	3AE 807 377	0%		£11.59
2620	R/R BUMPER GUIDE	3AE 807 378	0%		£11.59
2640	REAR BUMPER SUPPORT	3AA 807 305	0%		£142.39
2645	RR BUMPER MOULDING	3AE 807 863	0%		£20.91
3281	L/R OUTER LAMP	3AE 945 095 F	0%		£127.37
3282	R/R OUTER LAMP	3AE 945 096 F	0%		£127.37

Assessment Number: GW035469
Version: VBRA62M/1

Summary Report
Printed: 11/08/2021

Sub Total	£1,089.16
Sundry Parts	(2.5 %)
Total Parts	£27.23
	£1,116.39

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras			
Description		Betterment	Price
CAR CARE KIT	Specialist	0%	£4.75
E.P.A. CHARGE	Specialist	0%	£15.00
ODIS	PRE AND POST	0%	£150.00
COVID OVERHEADS	Specialist	0%	£20.00
Total Extras			£189.75

Calculation 11/08/2021

Labour			
	Total Panel/Mechanical	£181.50	
	Total Paintwork	£209.00	
Total Labour			£390.50
Total Paint/Material Costs			£437.47
Total Parts			£1,116.39
Additional Costs			
	Cost of Specialist	£189.75	
Total Additional Costs			£189.75
Grand Total Excl VAT			£2,134.11
	VAT @ 20 %		£426.82
Grand Total Incl VAT			£2,560.93
	Excess		£0.00

Assessment Notes

No assessment notes entered.

This is a brief summary of a full Audatex assessment. The full details are available.