

URGENT NEW INSTRUCTION

Instruction Details

To: Collision Engineers
Date: 06/05/2026
From: Smart Business Link
Introducer: MAGNA ACCIDENT SERVICES LIMITED

Claim & Policyholder

Claim Number: SBL-B0558371
Incident Date: 26/04/2026
Claim Type: Credit Repair
Driver: Mr EDSB Ltd EDSB Ltd
Policyholder Name: Mr EDSB Ltd EDSB Ltd
Policyholder VAT Status: VAT Registered
Address: E D S B Ltd Unit 2 Meadow Court 124 Millshaw Leeds, LS11 8LZ
Tel Mobile: 07786029293 Driver

Vehicle & Damage

Vehicle Make: VOLKSWAGEN ID4 PRO MATCH
Engine Size:
Registration: DA75 JCU
Vehicle Driveable: Yes
Vehicle Damage: Wheel scratched and trims around wheel scuffed scraped and scratched
Pre-Existing Damage:
Incident Circumstances: Our client was driving down the road when a driver came out of their driveway into the side of my vehicle at low speed. The driveway was on the left of our vehicle and hit the rear nearside. The third-party accepted fault. There was no emergency services
Agreed Value:
Current Vehicle Location: In use

Repairer Details

Repairer Name: Paynes Of Hinkley Arc
Repairer Address: Watling St Hinckley
Repairer Tel:
Repairer Email: arc@paynesgarages.co.uk
Agreed Labour Rate:

Insurance & Hire

Insurance Cover: Comprehensive
Policy Excess: £0
Authorise if in order?: Yes
Hire Supplied:
Hire Company:
Hire Out Date:

Important Notes

Please confirm by return receipt of instruction. Arrange inspection within 24 hours and provide full report within 48 hours.