



# SUREAUDIT INSTALLATION REPORT

Author: Asimuddin  
Mohammed  
Report No: 20  
Date: 21 Nov 2025

## Installation Details

1)	Client Name	rttt
2)	Category	trtrrt
3)	GPS Location	1600 Amphitheatre Pkwy, Mountain View, CA 94043, USA

## Vehicle Images



car image

## Vehicle Details

1)	Model	tyyy
2)	Plate Number	566
3)	Chassis Number	yyy
4)	Vehicle Type	rttt
5)	Vehicle Color	Gray

## Hardware Details

1)	serial_number	455
2)	sim_serial_number	8997112212776217952
3)	mobile_number	971831008675738
4)	RFID_number	0006150836 093,55988
5)	RFID_code_forward	01B4DA5D003100A9
6)	RFID_code_reverse	A90031005DDAB401

7)	<b>accessories_seat_sensor</b>	No
8)	<b>accessories_relay</b>	No
9)	<b>RFID</b>	Yes
10)	<b>accessories_buzzer</b>	Yes
11)	<b>accessories_na</b>	No
12)	<b>device_location</b>	

### Connection Details

1)	<b>device_location</b>	ehind Odometer
2)	<b>battery_ignition</b>	No
3)	<b>battery_direct</b>	Yes
4)	<b>wiring_loop</b>	No

### Technician Signature

	<b>Name:</b> Jayesh Date & Time: 21 Nov 2025 10:44 This report confirms completion of GPS installation as per guidelines.
---	---