

INVOICE

BILL TO

M/s DOHA DRUG STORE

Ms. Silpa S Kartha

jenefer@dohadrugstore.com,qc@dohadrugstore.com,

Doha-Qatar

44058615

PROJECT/SITE

DOHA DRUG STORE (COLD ROOM AMC)

Bank Name: Commercial Bank of Qatar (Q.S.C.)

IBAN: QA64CBQA00000004580580187001

Account No.: 4580-580187-001

Swift code: CBQAQAQA
Branch: GRAND HAMAD STREET

DATE
24/03/2025
INVOICE NO.
1200047
PO NO.
AMC CONTRACT



#	DESCRIPTION الوصف	QTY الكمية	UNIT PRICE سعر الوحدة	TOTAL PRICE السعر الإجمالي
1	Settlement of Monthly Payment for Cold Room AMC Covering MARCH 2025	1	1333.00	1333.00
2				0.00
3				0.00
4				0.00
5				0.00
6				0.00
7				0.00
8				0.00
9				0.00
10				0.00
11				0.00
	Remarks / Payment Instructions:		SUBTOTAL	1333.00
	Beneficiary Details: Mitri Engineering Services		DISCOUNT	0.00
	Tel/Fax: +974 44876142 Doha - Qatar Bank Details:		Balance Due	QR1,333.00

Tel: 44459207 - Fax: 44780499 - P.O.Box: 23107 E-mail: mes@mes.qa - Web: www.mes.qa

RI ENGINEERING SERVICES W



Date:	; -	22/03/2025	Doha Drug Store Monthly Maintenance Checklist Walk-In Chiller	Report #
UNIT	T NO: 0F000139 UNIT-2			133
S.No.		DESCRIPT	TION OF MAINTENANCE ACTIVITIES	REMARKS
1	Clean the condenser coil properly.			Cleaned
2	Check the operation of LP/HP Switc	hes /Solenoid valve.		Checked
3	Check and clean condensate drain l	ine and tray.		Checked & Cleaned
4	Check the evaporator fans operatio	n.		Checked
5	Record operating amps of compress	sor.		5.4 amp
6	Compressor Cut-in Tempreature.			4.2 C Deg
7	Compressor Cut-out Tempreature.			5.8 C Deg
8	Inspect and tighten all loose electric	cal connections.		Checked
9	Check and verify compressor oil lev	el.		Checked
10	Check if there is any leak.			No any leak
11	Check refrigerant level.			Checked
12	Check evaporator Coil and clean win	rh brush if necessary		Checked
I	ARKS: UNIT IS WORKING IN GOOD CON	IDITION		- - - -
MES RAJU	technician name and signatu	re	client's representative name ad signature	-



Date:	-	22/03/2025	Doha Drug Store Monthly Maintenance Checklist Walk-In Chiller	Report #
UNIT	NO: 0H000954 - UNIT-1			134
S.No.		DESC	RIPTION OF MAINTENANCE ACTIVITIES	REMARKS
1	Clean the condenser coil properly.			Cleaned
2	Check the operation of LP/HP Switch	hes /Solenoid valve.		Checked
3	Check and clean condensate drain li	ine and tray.		Checked & Cleaned
4	Check the evaporator fans operation	n.		Checked
5	Record operating amps of compress	sor.		4.7 amp
6	Compressor Cut-in Tempreature.			4.4 C Deg
7	Compressor Cut-out Tempreature.			6.2 C Deg
8	Inspect and tighten all loose electric	cal connections.		Checked
9	Check and verify compressor oil leve	el.		Checked
10	Check if there is any leak.			Checked. No any leak
11	Check refrigerant level.			Checked
12	Check evaporator Coil and clean wir	rh brush if necessary		Checked & Cleaned
REMA	ARKS: UNIT IS WORKING IN GOOD CONI	IDITION		
MES RAJU	technician name and signatur	re	client's representative name ad signature	



UNIT NO: 000139 **Doha Drug Store** Report # Monthly Maintenance Checklist Date: 22. 03. 2024 Walk-In Chiller UNIT NO: REMARKS DESCRIPTION OF MAINTENANCE ACTIVITIES S.No. cleaned with Presson Clean the condenser coil properly. checked Check the operation of LP/HP Switches /Solenoid valve. checked and cleaned Check and clean condensate drain line and tray. Check the evaporator fans operation. checked Record operating amps of compressor. 5.4 A.M.P 4.2 C Compressor Cut-in Tempreature. Compressor Cut-out Tempreature. 5.8C Inspect and tighten all loose electrical connections. checked checked Check and verify compressor oil level. Leak Check if there is any leak. No any checked OK Check refrigerant level. cleaned checked and Check evaporator Coil and clean wirh brush if necessary REMARKS: working Normal

MES technician name and signature

Raju

for.

client's representative name ad signature

23.03.2025 Th



		UNII NO'- OHOO	954 / 01
Date	-22.03.2025	Doha Drug Store Monthly Maintenance Checklist Walk-In Chiller	Report #
ואר	NO:		
S.No.		DESCRIPTION OF MAINTENANCE ACTIVITIES	REMARKS
1	Clean the condenser coil properly.	cleaned with Pressor Pume	
2	Check the operation of LP/HP Switches /Solenoid valve. Check the operation of LP/HP Switches /Solenoid valve.		
3	Check and clean condensate drain line and tray.	checked and cleaned	
4	Check the evaporator fans operation.	cheeked	
5	Record operating amps of compressor.	4.7 A.M.P	
6	Compressor Cut-in Tempreature.	4.4 C ==	
7	Compressor Cut-out Tempreature.	6.2°C	
8	Inspect and tighten all loose electrical connections.	checked	
9	Check and verify compressor oil level.	checked	
10	Check if there is any leak.	No any Leak	
_	Check refrigerant level.	checked ox	
12	Check evaporator Coil and clean wirh brush if necess	checked and cleaned	
	RKS:		
	Unit work	ing Normal	
S tec	hnician name and signature	client's representative name ad signature Omer Donaken	
		29, 93, 2025	