## Building and deploying programs

- 1. Run the Makefile. Note that this may need to change if the simulator (assembler) location changes.
- 2. Run ../scripts/send\_bytes.py /dev/cu.usbserial-14401 filename.bin to deploy to the device
- 3.