

Assembly drawing SMD [TOP] Assembly drawing THT [TOP]

(M1) Board Outline

PASTEMASK (TOP)

C3 X2 # **|** | # C14 C10 C11 _ 111111111111111111 J9 J16 0 \bigcirc \bigcirc \bigcirc

Assembly drawing SMD [BOT]

(M1) Board Outline

PASTEMASK (BOT)