Date: 5/ 7/2014 01:45 PM

Page 1 of 3

Estimate ID: 70719
Estimate Version: 0
Preliminary
Profile ID: * A1

A-1 AUTO BODY LTD.

5304 - 1A STREET S.E., CALGARY, AB T2H 1J2 (403) 253-7867 Fax: (403) 252-7248

Damage Assessed By: MIKE. B @A1AUTOBODY Appraised For: C/P

Type of Loss: Collision

Payer: Customer Deductible: UNKNOWN

Claim Number: C/P-RR COVER

Owner: MIKE GEE

Address: 23 WALNUT DR SW, CALGARY, AB Telephone: Home Phone: (403) 589-0500

Mitchell Service: 911093

Description: 2009 Honda Pilot EX Vehicle Production Date: 6/08

Body Style: 4D Ut Drive Train: 3.5L Inj 6 Cyl AWD VIN: 2FNYF48949B501189 License: NUP485 AB

Mileage: 120,000

OEM/ALT: O Search Code: None

Color: GREY

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW

REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN, REAR (DUAL-ZONE) AC TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS

ALUM/ALLOY WHEELS, AUXILIARY INPUT, SATELLITE RADIO, TOW HITCH RECEIVER

FRONT AIR DAM, TINTED GLASS, AUTO AIR CONDITION, TRIP COMPUTER

THIRD ROW SPLIT BENCH SEAT, SUBWOOFER, UNIVERSAL GARAGE DOOR OPENER THIRD ROW REMOVABLE SEAT, VARIABLE ASSISTED STEERING, SIDE AIRBAGS

ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS

DAYTIME RUNNING LIGHTS, AM/FM STEREO CD CHANGER/MP3 PLAYER

ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, INTERIOR AIR FILTER KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER HEATED EXTERIOR MIRRORS POWER LIFTGATE\TRUNK, REAR AC & HEATER, REAR SPOILER, REAR WINDOW WIPER SECOND ROW SPLIT FOLDING BENCH SEAT, STEERING WHEEL AUDIO CONTROLS

Line	Entry	Labor		Line Item	Part Type/	Dollar	Labor
Item	Number	Туре	Operation	Description	Part Number	Amount	Units
1	103210	BDY	REMOVE/REPLACE	R Quarter Exhaust Vent	75450-SMA-003	24.06	0.2 #
2	AUTO	BDY	REMOVE/INSTALL	Rear Bumper Cover			INC
3	900500	BDY *	REPAIR	PULL&REPAIR RT 1/4 PNL UNDER COVER	Existing		4.0*
4	900500	REF *	REFINISH/REPAIR	SPOT PAINT UNDER COVER	Existing		0.5*
5	900500	REF *	REFINISH/REPAIR	FLEX AGENT & ADHESION PROMOTER	Sublet	15.00 *	0.0*
6	AUTO	BDY	OVERHAUL	Rear Bumper Cover Assy			1.7
7	102396	BDY	REMOVE/REPLACE	Rear Bumper Cover	Remanufactured	350.00 *	INC
8	AUTO	REF	REFINISH	Rear Bumper Cover		(2.6 #
9				**POSS SENSOR/REBAR DAMAGE**			
10	102423	BDY	REMOVE/REPLACE	R Rear Bumper Spacer	71593-SZA-A00	5.36	INC
11	AUTO	REF	ADD'L OPR	Clear Coat			1.0
12	933004	BDY	ADD'L OPR	UNDERCOATING		25.00 *	0.3*
13	AUTO		ADD'L COST	Paint/Materials		151.70 *	!
14	AUTO		ADD'L COST	Shop Materials		72.00 *	!
ES.	TIMATE RE	ECALL NU	JMBER: 05/07/2014 13:4	5:13 70719			

ESTIMATE RECALL NUMBER: 05/07/2014 13:45:13 70719

7.1.164

Mitchell Data Version: OEM: APR 14 V

Software Version:

Copyright (C) 1994 - 2014 Mitchell International

All Rights Reserved

Date: 5/ 7/2014 01:45 PM

7.50 *

Estimate ID: 70719 **Estimate Version:** 0 **Preliminary**

Profile ID: * A1

15 **AUTO** ADD'L COST

Hazardous Waste Disposal

* - Judgment Item

- Labor Note Applies

C - Included in Clear Coat Calc

Remarks

SOURCE; REPEAT D/S-N/N LESS THAN \$2000

**POSS ADDT'L 1/4 PANEL DAMAGE, VIEW WHEN APART

Estimate Totals

I.	Labor Subtotals Body Refinish	Units 6.2 4.1 Taxable L		Add'I Labor Amount 25.00 0.00	Sublet Amount 0.00 15.00	Totals 459.00 T 302.00 T 761.00 38.05	II.	Part Replacement Summary Taxable Parts GST - I Tax Total Replacement Parts Amou	@ unt	5.000%	Amount 379.42 18.97 398.39
	Labor Summary	10.3				799.05					
III.	Additional Costs Taxable Costs Total Addition Paint Material Init Rate = 37.	GST - I Tax nal Costs I Method: Ra	tes		5.000% ate = 22.00	Amount 231.20 11.56 242.76	IV.	Adjustments Customer Responsibili	ty		Amount 0.00
							I. II. III.	Total Labor: Total Replacement Parts: Total Additional Costs: Gross Total: Total GST:			799.05 398.39 242.76 1,440.20 68.58
							IV.	Total Adjustments: Net Total:			0.00 1,440.20

This is a preliminary estimate. Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

5 Right Rear Corner (P)

Insurance Co: C/P

ESTIMATE RECALL NUMBER: 05/07/2014 13:45:13 70719

Mitchell Data Version: OEM: APR_14_V

Copyright (C) 1994 - 2014 Mitchell International

Software Version: 7.1.164 **All Rights Reserved** Page 2 of 3

Date: 5/ 7/2014 01:45 PM Estimate ID: 70719 Estimate Version: 0 **Preliminary** Profile ID: * A1

Inspection Date: 5/7/2014

Body Shop: A-1 Autobody Address: 5304 1A St SE

Calgary, AB T2H 1J2

Telephone: (403) 253-7867 Fax Phone: (403) 252-7248

THIS IS A VISIBLE DAMAGE QUOTATION ONLY.

***** NOTICE ****

NO GUARANTEE AGAINST PAINT MATCH OR PEELING IF NECESSARY PARTS & TRIM ARE NOT REMOVED AND BLENDING TIME NOT ALLOWED.

Cycle Time Information

Repair Dates:

Start Date: 5/ 7/2014 Promise Date: 5/ 7/2014

ESTIMATE RECALL NUMBER: 05/07/2014 13:45:13 70719

Mitchell Data Version: OEM: APR_14_V

Copyright (C) 1994 - 2014 Mitchell International Page 3 of 3 **Software Version:** 7.1.164

All Rights Reserved