Changes in version 02.02.249

SIGMATEK

Error Corrections

Reason for change:
8D-9332:
Loader message about ObjectChannel
When LDR_LookupEmbedded is called, an error message appears in the debugger trace window if the name is an Advanced IO element.
Risk assessment of the Error:
no risk
Type of change:
The LDR_LookupEmbedded function in the loader has been changed so that no error message appears in the debugger trace window when it is called with the name of an Advanced IO element.
Affected area:
LOADER