
Start Window (scan view)



- load a scanned image, by either typing the path or browsing for it
- 2. select an area by either putting in the coordinates or using the selction tool
- (2.5) show statistic for a color, e.g. average value of an unirradiated area to get a phi_0
- 3. select the calibration to use, set DPI (for getting the cm scale) and phi_0, click show dose to get the dose picture

Logging area:

Shows errors and warnings from the program as well as all the ouput, e.g. from the area stats.

dose view

