


Table 1: Rating scale to assess the extent of fouling on inspection areas

Rating	Description	Macrofouling cover of area inspected (visual estimate)	Recommended cleaning
0	No fouling Surface entirely clean. No visible biofouling on surfaces.	-	-
1	Microfouling Submerged areas partially or entirely covered in microfouling. Metal and painted surface may be visible beneath the fouling.	-	Proactive cleaning may be recommended as further specified in paragraph 9.4.
2	Light macrofouling Presence of microfouling and multiple macrofouling patches. Fouling species cannot be easily wiped off by hand.	1-15% of surface	Cleaning with capture is recommended as further specified in paragraph 9.9.
3	Medium macrofouling Presence of microfouling and multiple macrofouling patches.	16-40% of surface	It is recommended to shorten the interval until the next inspection. If the AFS is significantly deteriorated, dry-docking with maintenance and reapplication of the AFS is recommended.
4	Heavy macrofouling Large patches or submerged areas entirely covered in macrofouling.	41-100% of surface	

Biofouling Rankings



Percentage Cover %

