

SQ HUES LTD

STANDARD OPERATING PROCEDURE (SOP)

Department: QA

Process Name: Final Finish Fabric Inspection

- Before final Inspection inspector will check the batch card information to check the online report.
- Then the helping elements such as scissor, measuring tape, sticker, inspection report, poly bag etc. should be ready.
- After getting the final confirmation from the Executive, inspector will start the inspection.
- Inspector read the batch card for general information and write the relevant information to the blank inspection report
- Then start inspection according to 4-point system.
- From the first roll cut the GSM swatch in 3 places and check either its ok or not ok, If not ok found then for better understanding check again 3 places, if re-check GSM found not ok then hold this batch to inspect & inform to superior /Executives for final decision.
- Check the width from beginning, middle & ending of 1st roll.
- Cut swatches from every roll for making GSM & SHADE Continuity.
- If any aesthetic problem found during inspection, inform to superior/executive for final decision
- After completing full batch inspection, prepare GSM board, roll to roll continuity and complete 4-point inspection report.
- Keep relevant fabric swatch for any commercial approval.
- After completing full batch documentation Executives/ Quality Manager will provide the decision for final dispatch of the fabrics. PASS fabric will handover to HUES store and Reject fabrics will keep in the rejection area.
- Intensity of the inspection area must be above 1000 LUX.