Hold

ID:		
451		
Part Number:		
SST-1009		
Discrepancy:		
only got through half a steam cycle due to	equipment failure	
Issued By:		
Meholick, An		
Issued Date:		
08/27/2025	DE 05	
	RE-STI	EAM TREAT
Corrective Action Needed: Yes No	RUN T	EST FIRST
Amount:		
3 barrel		

Return Form To QA Manager Once Completed