

Repair Services Pricing

(Effective January 1, 2013)

Repair Services: Model #'s CT-CT1000 and CT-CT1010

All repairs must obtain an RMA (Return Merchandise Authorization) number from CryoPen, Inc. Please call 1-877-246-3955 to obtain an RMA before returning an item. A Standard Evaluation and Shipping fee will apply and is payable by credit card in advance.

Pricing for out of scope or out of warranty repairs:

Standard Evaluation (Includes Shipping)		
If the customer authorizes the recommended repairs,	\$425.00	
\$75 of this fee will be applied towards the cost of the repairs.		

Replacement Fees			
CT-1010-01	Replacement Cooler - New	\$1200.00 (12 mos. Warranty)	
CT-1010-02	Replacement Cooler - Refurbished (if available)	\$750.00 (3 mos. Warranty)	
CT-1010-03	Replacement Power Supply	\$150.00	
CT-1010-04	Replacement Control Board	\$100.00	
CT-1010-05	Replacement TW Board	\$200.00	
CT-1010-06	Replacement Tower	\$400.00	
CT-PA-1000-7	Replacement Handheld Modules (each) 7mm	\$225.00	
CT-TI-1000	Replacement Temperature Indicator	\$325.00	
CT-TA-5003, 5005 ,5007, 5010		\$225.00	
Replacement Tips (3 per pack: Sizes 3, 5, 7, 10 mm)			
CT-1010-07	Replacement Top Case - Refurbished	\$300.00	
TI-EX-3	Temperature Indicator Exchange Program	\$65.00 (includes shipping)	
Additional Repairs (All repairs are warranted for 90 days from date of		TBD during evaluation	
repair, unless ot	herwise stated)		
Non – Returned Shipping Case			
This fee is charged to the customer when the case is not		\$500.00	

CryoPen, Inc • P.O. Box 2907 • Corpus Christi, TX 78403 Tech Support: 877-246-3955

received back to CryoPen, Inc.'s Repair facility within 14 days of

original shipment of repaired unit.