## Permeate Conductivity Experiment 7 1000 Permeate Conductivity 750 Measure High 500 Low 250

