04820KA001 Mono Slitter 903_V12_1110_2

Author: Michou
Created: 11/10/2026 2:48:15 PM
Last Modified: 11/10/2026 2:48:15 PM
Comment: Modified to Connect 2nd Diameter Sens

Sysmac Studio Module Version: 1.60.0.64010

Table of Contents

04820KA001 Mono Slitter 903_V12_1110_2	3
1.PLC	3
1-8.POUs	3
1-8-1.Programs	3
1-8-1-1.TaglMonoTRM	3
1-8-1-1-5.Console	3

1.PLC

1-8.POUs

1-8-1.Programs

1-8-1-1.TaglMonoTRM

1-8-1-5.Console

0 Variables of type 'TIME'.

```
1  TimStopVen := NanoSecToTime(REAL_TO_LINT(Fan_Timeout * REAL#60000000000));
2  TimPosPresOn := NanoSecToTime(REAL_TO_LINT(OverRider_TimeON *
   REAL#1000000000));
3  TimPosPresOff := NanoSecToTime(REAL_TO_LINT(OverRider_TimeOFF *
   REAL#1000000000));
```

1 Convert the pulses into mm and m.

```
1  Current_mm := DINT_TO_REAL(Encoder_Pos) * EncoderPulse_to_mm;
2  Current_Metre := Current_mm / REAL#1000;
```


2 Motor Stop





3 Request to reset the meter counter.




4 Password check..




DINT#48
In
Out
HMI_Screen[0]
HMI pan...
5
<>
EN
Psw
Password Entry
INT#44
In1
In2
<>
EN
Psw
Password Entry
INT#48
In1
In2
15
Psw22
7
Password 22 for Popup 22
1
MOVE
EN ENO
12
DINT#22
In
Out
HMI_Screen[0]
HMI pan...
Psw33
8
Password 33 for Popup 33
2
MOVE
EN ENO
13
DINT#33
In
Out
HMI_Screen[0]
HMI pan...
Psw40
11
Password 40 for Popup 40
Psw44
9
Password 44 for Popup 44
3
MOVE
EN ENO
14
DINT#44
In
Out
HMI_Screen[0]
HMI pan...
Psw48
10
Password 48 for Popup 48


15
<>
EN
Psw
In1
Password Entry
INT#0
In2
Up
In
MOVE
EN ENO
INT#0
In
Out
Psw
Password Entry
MOVE
EN ENO
DINT#10
In
Out
HMI_Screen[0]
HMI pan...
12
13
6
14
4


5
Password Reset
P_First_RunMode
First RUN Period Flag
MOVE
EN ENO
INT#0
In Out
Psw
Password Entry
T_Screen_Delay
=
EN
TON
In Q
HMI_Screen[0]
HMI pan...
DINT#10
In1
In2
T#1ms
PT ET
6
HMI coding.
P_On
Always TRUE Flag
MOVE
EN ENO
Alarm_Array
Alarms
In Out
AlarmCodeSV
Panel alarms
I_Prot_ByPass
In_4 Guards-bypassed selector switch - Under Panel
SafeGuard_ByPass
Guards bypassed
I_FrontGuard_Closed
In_6 Front guard closed
FrontGuard_Closed
Front guard closed