A. Operations

- 1. Test all operations
- 2. Execute every operation after every operation
- 3. Execute reset after every operation
- 4. Execute reset before every operation

B. Data

- 1. Simulate minimum value of input operand for every operation
- 2. Simulate maximum value of input operand for every operation

C. Errors

- 1. Test sending incomplete data
- 2. Use invalid operation code
- 3. Test sending incorrect CRC