

Customer Name

: PT THIESS

Ref (WO / AN)

: - / -

Unit Model

: CAT 785C

PO Number

: -

No	Part Description	Part Number	Qty
1	-	160-5899	1

Labor Cost	Rp 200.000
Material Cost	Rp 599.999
Total Amount	Rp 799.999

Estimated Completion: 2026-07-22

Remarks: -

REPAIR PROCEDURE

- Disassembly and cleaning of all components.
- Visual inspection and dimensional measurement.
- Replacement of damaged or worn-out parts.
- Reassembly and final testing according to standard specifications.

STANDARD TERMS & CONDITIONS

1. The above pricing excludes PPN.
2. Pricing includes pick up and delivery within the Balikpapan area if required.
3. In the event that there is any indication of faulty workmanship within the normal service life of the component, repairs to the faulty work will be carried out free of charge.
4. Liability for any damage of the components at PT RAF ROBIAN TEHNIK premises or during transit by PT RAF ROBIAN TEHNIK, or subsequent consequential losses caused by such damage or loss is excluded.
5. Pricing validity: 30 days from date of this quotation.
6. Terms of payment : 30 days following received date of Invoice.

Prepared By,

Approved By,

PT RAF ROBIAN TEHNIK

PT THIESS

Generated automatically by Repair Monitoring Information System (RMIS).