

Release Notes for SPC1068 Standard Peripherals Library Drivers

V1.2.0/ 5-February-2021

Main Changes

- clock.h/.c
 - Add 3 macro definitions: __RCO0_CLOCK, __RCO1_CLOCK and PLL_MAX_FREQ.
 - Update member values of enum definition: CLOCK ModuleEnum, CLOCK HCLKSelEnum.
 - Update 1 macro function: CLOCK_MODULECTL().
 - Update 4 functions for controlling module clocks: CLOCK_GetModuleClk(), CLOCK_GetModuleDiv(), CLOCK_EnablePWMModule() and CLOCK_GetPWMModuleDiv().
 - Update 4 functions for clock initialization: CLOCK_Init(), CLOCK_InitWithRCO(), CLOCK_PLLConfig() and CLOCK_PLLQuickConfigWithRCO().
 - Remove 1 macro definition: RCO CLOCK HZ.
 - Remove 5 global variables: _XO_CONNECTED_FLAG_, gau32PLL_Array, gau8HCLK_DIV_Array, gau8PCLK_DIV_Array and gau8ADC_DIV_Array.
- comp.h/.c
 - Update 1 function: COMP_SetDeglitchTimeNs().
- flash.h/.c
 - Update 4 functions for compatible with SPC1068G OTP operation: FLASH_EraseOTP(), FLASH_ReadOTP(), FLASH_WriteOTP() and FLASH_LockOTP().
 - Update member values of FLASH_ProtectionEnum definition.
- wdt.c
 - Update 1 function: WDT_Init().
- ssp.c
 - Update 2 functions: SSP_Init() and SSP_InitEasy().
- spc1068_bitfield.h
 - Update UARTLCR.WLS and UARTLCR.STB label definitions.
 - Rename macro definition ADCSOCxCTL_YYYYYY to ADCSOCCTLx_YYYYYY (x= 0~15).
- startup_spc1068.s
 - Update Reset_Handler() and add code to reset stack pointer.

©2021 Spintrol Limited 1/2



V1.1.1/ 6-June-2019

Main Changes

- adc.h
 - Update 1 macro function: ADC_GetTrimResult1().
- clock.h
 - Update 1 macro definition: CLOCK_MODULECTL().
- gpio.h
 - Update 1 macro function: PINMUX_GPIO().
- spc1068.h
 - Rename macro function abs() to ABS().
- Support IAR EW for ARM.

V1.1.0/ 9-August-2018

Created.