Sheet1

INPUT CONI PIN 1 2 3 4 5 6 7 8	NECTOR PIN (HEAI COMPONENT 5V 5V 5V 5V 5V 5V 5V 5V	DER SIDE/ bottom side COMPONENT PIN	e, follow IDE numb LED	pering pin1 i
10				
11	74HC373(U4)	18(D7)	pin11(C3)	
12	74HC373(U4)	17(D6)	pin10(C4)	
13 14	74HC373(U4) 74HC373(U4)	14(D5) 13(D4)	pin6(C5) pin13(C1)	
15	74HC373(U4)	8(D3)	pin13(C1)	
16	74HC373(U4)	7(D2)	pin11(C3)	
17	74HC373(U4)	4(D1)	pin10(C4)	
18	74HC373(U4)	3(D0)	pin6(C5)	
19	74HC245(Ù22)	12(B7)	,	
20				
21 22	74HC237(U15)	2(A1)		2 <sup>nd</sup> o
23	74HC245(U22)	16(B3)		
24	74HC245(U22)	15(B4)		
25	74HC237(U15)	3(A3)		3 <sup>rd</sup> pin
26	74HC237(U15)	1(A0)		1st o
27	GND			
28	GND			
29	GND			
30	GND			
31	GND			
32 33	GND GND			
33 34	GND			
J <del>-1</del>	OIND			

s 5V)

**ROLE** 

D7->Q7->LED\_PIN11(J9)
D6->Q6->LED\_PIN10(J9)
D5->Q5->LED\_PIN6(J3)
D4->Q4->LED\_PIN\_13(J2)
D3->Q3->LED\_PIN3(J1)
D2->Q2->LED\_PIN\_11(J2)
D1->Q1->LED\_PIN\_10(J2)
D0->Q0->LED\_PIN\_6(J1)
goes to GAL

f 3 pins used to select row to be lit up (scanned)

of 3 pins used to select row to be lit up (scanned) f 3 pins used to select row to be lit up (scanned)