







	Α	В	
Contacts	A±0.20	B±0.10	Remark
06	7.62	5.08	Without Middle Bar
08	10.16	7.62	
14	17.78	15.24	
16	20.32	17.78	
18	22.86	20.32	
20	25.40	22.86	
22	27.94	25.40	
24	30.48	27.94	With Middle Bar
28	35.56	33.02	
32	40.64	38.10	