## 2022-05-24 18:15:17 - Validation Report: FAIL

**BGP - PASS** 

DHCPRelay - PASS

LLDP - FAIL

- No LLDP IEEE 802.1 VLAN Name (Subtype 3) Founded

**VLAN - PASS** 

```
TimeDate: 2022-04-27T22:51:42.982572Z
ResultSummary:
  BGP - PASS: []
  DHCPRelay - PASS: []
  LLDP - FAIL:
   - No LLDP IEEE 802.1 VLAN Name (Subtype 3) Founded
  VLAN - PASS: []
VLANResult:
  vlanids:
   - 710
   - 711
   - 712
LLDPResult:
  sysdes: "Dell EMC Networking OS10 Enterprise.\r\nCopyright (c) 1999-2021 by Dell
     Inc. All Rights Reserved.\r\nSystem Description: OS10 Enterprise.\r\nOS Version:
     10.5.3.0.\r\nSystem Type: S5248F-VM"
  portname: ethernet1/1/1
  chasisid: 0cc23e6c0000
  chasisidtype: MAC Address
  vlanid: 710
  ieee8021subtype3: []
  mtu: 9214
  ets:
    etstotalpg: 8
    etsbwbypgid:
       0:48
       1:0
       2: 0
       3:50
       4: 0
       5: 2
       6:0
       7:0
  pfc:
     pfcmaxclasses: 8
    pfcpriorityenabled:
       0:0
       1:0
       2:0
       3: 1
       4:0
       5:0
       6:0
       7:0
DHCPResult:
  dhcppacketdetected: true
  relayagentip: 10.10.12.1
BGPResult:
  bgptcppacketdetected: true
  switchinterfaceip: 10.10.10.1
  switchinterfacemac: 0c:c2:3e:6c:00:a1
  hostinterfaceip: 10.10.10.11
  hostinterfacemac: 0c:11:4a:d6:00:01
```