## 2023-01-06 15:11:27 - Validation Report: FAIL

**BGP - FAIL** 

- TCP 179 Packet Not Detected from switch

DHCPRelay - FAIL

- DHCP Relay Agent IP Not Detected from switch

LLDP - PASS

**VLAN - PASS** 

```
TimeDate: 2022-11-06T05:22:06.701322Z
ResultSummary:
  BGP - FAIL:
     - TCP 179 Packet Not Detected from switch
  DHCPRelay - FAIL:
     - DHCP Relay Agent IP Not Detected from switch
  LLDP - PASS: []
  VLAN - PASS: []
VLANResult:
  nativevlanid: 1
  allvlanids:
    - 1
    - 710
    - 711
    - 712
LLDPResult:
  sysdes: Cumulus Linux version 5.2.1 running on Mellanox Technologies Ltd. MSN2100
  portname: swp1
  chasisid: 98039b5cbb20
  chasisidtype: MAC Address
  subtype1_portvlanid: 1
  subtype3_vlanlist:
    - 1
    - 710
    - 711
    - 712
  subtype4_maxframesize: 9214
  subtype7_linkaggcap: true
  subtype9_ets:
     etstotalpg: 8
    etsbwbypgid:
       0:48
       1:0
       2: 0
       3:50
       4: 0
       5: 2
       6:0
       7: 0
  subtypeb_pfc:
     pfcmaxclasses: 8
    pfcconfig:
       0:0
       1:0
       2: 0
       3: 1
       4: 0
       5: 0
       6:0
       7:0
DHCPResult:
  dhcppacketdetected: true
  relayagentip: ""
```

BGPResult:

bgptcppacketdetected: false

switchinterfaceip: "" switchinterfacemac: "" hostinterfaceip: "" hostinterfacemac: "" interfacename: eth1 nativevlanid: 1

allvlanids: - 1

- 710

- 711

- 712

mtusize: 9214 etsmaxclass: 8

etsbwbypg: 0:48,1:0,2:0,3:50,4:0,5:2,6:0,7:0

pfcmaxclass: 8

pfcpriorityenabled: 0:0,1:0,2:0,3:1,4:0,5:0,6:0,7:0