2022-05-21 22:11:40 Validation Result Summary:

BGP - PASS

DHCPRelay - PASS

LLDP - FAIL

- Incorrect Maximum Frame Size Input:9214, Found: 9216
- Incorrect Port VLAN ID VLANLIST:[], Found: 710
- Incorrect ETS Class Bandwidth Configured:

Input:0:48,1:0,2:0,3:50,4:0,5:2,6:0,7:0

Found: 0:46,1:1,2:1,3:48,4:1,5:1,6:1,7:1

```
TimeDate: "2022-05-21 22:11:40"
ResultSummary:
  BGP - PASS: []
  DHCPRelay - PASS: []
  LLDP - FAIL:
   - 'Incorrect Maximum Frame Size - Input:9214, Found: 9216'
   - 'Incorrect Port VLAN ID - VLANLIST:[], Found: 710'
    Incorrect ETS Class Bandwidth Configured:
      Input:0:48,1:0,2:0,3:50,4:0,5:2,6:0,7:0
      Found: 0:46,1:1,2:1,3:48,4:1,5:1,6:1,7:1
VLANResult: {}
LLDPResult:
  sysdes: "Dell EMC Networking OS10 Enterprise.\r\nCopyright (c) 1999-2021 by Dell
     Inc. All Rights Reserved.\r\nSystem Description: OS10 Enterprise.\r\nOS Version:
     10.5.3.0.\r\nSystem Type: S5248F-VM"
  portname: ethernet1/1/1
  chasisid: 0cc23e6c0000
  vlanid: 710
  mtu: 9216
  ets:
     etstotalpg: 8
    etsbwbypgid:
       0:46
       1:1
       2: 1
       3:48
       4: 1
       5: 1
       6: 1
       7: 1
  pfc:
     pfcmaxclasses: 8
    pfcpriorityenabled:
       0:0
       1:0
       2:0
       3: 1
       4:0
       5:0
       6:0
       7:0
DHCPResult:
  dhcppacketdetected: true
  relayagentip: 10.10.12.1
BGPResult:
  bgptcppacketdetected: true
  switchinterfaceip: 10.10.10.1
  switchinterfacemac:
   - 12
   - 194
   - 62
   - 108
```

- 0
- 161

hostinterfaceip: 10.10.10.100

hostinterfacemac:

- 12
- 176
- 153
- 74
- 0
- 1