Part Board - B

Cut out as change and 2 stud were added