

Summary

Starting Point	
End Point	
Total no. of Issues	39
Rust	5
Bird Drop	4
Truss Tilted	2
Jumper Twisted	1
Insulator Broken	1
Damaged or cracked	6
Anchor bolt rusting.	1
Isolate Moving Handle	1
Bracket assembly rusted	9
Catenary Suspension Clamp Rusted	4
Stay insulator chipped/damaged/flashed	2
Bracket insulator chipped/damaged/flashed	3

Summary

Anomalies



- Rust
- Bird Drop
- Truss Tilted
- Jumper Twisted
- Insulator Broken
- Damaged or cracked
- Anchor bolt rusting.
- Isolate Moving Handle
- Bracket assembly rusted
- Catenary Suspension Clamp Rusted
- Stay insulator chipped/damaged/flushed
- Bracket insulator chipped/damaged/flushed