

Service Bulletin SB-2026-04 - Display Software Update

Document ID: SVT-DEMO-RAG | Classification: Internal Advisor Use

Subject

Intermittent display flicker on Stride 200 Demo TFT cluster.

Affected Models

SVT Stride 200 Demo - production batch SV-DEMO-2025-Q4.

Symptom

Brief flicker on startup in hot weather (>38°C).

Advisor Action

Inform customer. Schedule software update at authorised dealer. No safety recall - convenience fix.

Demo Reference Rider

Check Ananya Rao service history for related workshop notes in Module 1 demo.