```
Coodinator → Enddevice へのユニキャスト通信に成功. (ポーリングあり)
  uint64 unicastMacAddr = 0x001BC50122016BDD;
  eStatus=ZPS_eAplAfUnicastIeeeDataReq( //ユニキャスト通信
                                  hAPduInst,
                                   0x1337,
                                   0x01,
                                   0x01,
                                  unicastMacAddr, //Dest: 64bit-Enddevice
                                   eSecurityMode,
                                   &u8TransactionSequenceNumber
                                   );
 Problems Console Properties Router PendDevice Coordinato
 Serial: (COM6, 115200, 8, 1, None, None - CLOSED) - Encoding: (ISO-8859-
 APP: Woken up (CB)
 APP: Polling for data
 APP: No event to process
 APP: APP_taskEndPoint: ZPS_EVENT_AF_DATA_INDICATION
     Data Indication:
         Profile :1234
         Cluster:1337
         EndPoint:1
 received data: FromCoordinator
 APP: No event to process!
App_sleeping_enddevice.c の WakeUp と Sleep になる部分をコメントアウトする.
vWaitForNetworkDiscovery 関数と
vWaitForNetworkJoin 関数と
vHandleStackEvent 関数の
                        PWRM eScheduleActivity 関数をコメントアウト
  s_eDeviceState.eNodeState = E_RUNNING;
  /* set device to go to sleep */
  //コメントアウト
  //PWRM_eScheduleActivity(&sWake, SLEEP_TIME, vWakeCallBack);
このテンプレートは WakeUp と Pulling と Sleeping が同時に実行されている.
```

```
🕮 Problems 🔍 Console 🖾 Properties 🧬 Router 🖑 EndDevice 🦑 Coordinator69
      Serial: (COM5, 115200, 8, 1, None, None - CLOSED) - Encoding: (ISO-8859-1)
              APP_taskEndPoint: ZPS_EVENT_AF_DATA_INDICATION
            Data Indication:
                  Profile :1234
Cluster :1337
                  EndPoint:1
       received data:FromRouterrrr
      APP: VCheckStackEvent: unhandled event 29
APP: APP_taskEndPoint: ZPS_EVENT_AF_DATA_INDICATION
    Data Indication:
                  Profile :1234
Cluster :1337
                  EndPoint:1
      received data:FromRouterrrr

APP: VCheckStackEvent: unhandled event 29

APP: APP_taskEndPoint: ZPS_EVENT_AF_DATA_INDICATION

Data_Indication:
                  Profile :1234
                  Cluster :1337
                  EndPoint:1
      received data:FromEndDevice
      send
      Sending : FromCoordinator
lone - CLOSED) - Encoding: (ISO-8859-1)
```

Router → Coordinator, Enddevice → Coordinator のユニキャスト通信は成功. Coordinator → Router → Enddevice のユニキャスト通信はできていない.

ポーリングをしていないため、Coordinator \rightarrow Router、Coordinator \rightarrow Enddevice の通信もできていない.

コードをかえてなく、接続手順も同じであるのに、うまくいく時といかない時がある. 下の図のように、ZPS_eAplZdoPoll を入れるとループになるため、失敗.

```
case ZPS_EVENT_NWK_POLL_CONFIRM:
{
    DBG_vPrintf(TRACE_APP, "APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = %d\n", sStackEvent.uEvent.sNwkPollConfirmEvent.u8Status);
    //コメントアウト
    // PWRM_eScheduleActivity(&sWake, SLEEP_TIME, vWakeCallBack);

    ZPS_eAplZdoPoll();
}
break;

case ZPS_EVENT_NWK_FAILED_TO_JOIN:
{
    s_eDeviceState.eNodeState = E_STARTUP;
}
break;

Problems © Console Properties FRouter FEndDevice © FCoordinator69

Senal: (COM6, 115200, 8, 1, None, None - CLOSED) - Encoding: (ISO-8859-1)
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: NO event to process!
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: No event to process!
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: No event to process!
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: No event to process!
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: No event to process!
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: No event to process!
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: No event to process!
APP: vCheckStackEvent: ZPS_EVENT_NEW_POLL_COMPLETE, status = 235
APP: No event to process!
```

(想定環境の確認)




図 1 想定環境の全体図




図 2 屋上のネットワーク

部屋にあるユーザ端末が、ベランダにある Coordinator かつシンクにアクセスしデータ取得ベランダのシンクには、屋上の Router ともう一つの Router を介して、データが集まる. 屋上の Router には、作物に設置してあるセンサ端末のデータが集まる.

疑問点として

センサ端末が Enddevice とするならば、1 ホップで各センサ端末が Router に送信しなければならない。図のようにマルチホップを形成するならば、1つ1つのセンサ端末は Router なのか?

①マルチホップを使用するメリット

WI-Fi だと壁の障害物の影響を受けるため、壁を迂回できるようマルチホップを使用 どれかセンサ端末1つが故障しても Router やシンクに送信できるようセンサ端末同士も.

②ZigBee を使用するメリット

屋上の作物には沢山の種類や数のセンサ端末をしようするので、安価で多数接続可能の ZigBee を使用する. また, 小規模農業をターゲットとしているので、低コストの ZigBee を 採用する.