

355 N DELAWARE ST PO BOX 30 NAPPANEE IN 46550-0030 (574) 773-7791 FAX (574) 773-7798

PACKING SLIP

PAGE

SHIP TO:

WARD-413080-RW21

12/09/22

6505 SHRESBURY LANE DUBUQUE IA 52003

USA

CUSTOMER COPY

DATE: 12/08/22

DUE ON: 12/08/22

EXPORT:

N

SOLD TO:

MIKE WARD 12-5-22

MIKE@WARDFARM.ORG

413080 2017 VTDP 3412

4UZACHDT9HCJG9420 DOP 2-10-17

734-272-1434

NAPPANEE IN 46550

USA

TERMS:

Return part accompanied by this FORM must be returned to Newmar within 90 days of original receipt of the part and in accordance with the Newmar Parts Ordering Guidelines.

CUSTOMER		ORDER NO. SLS REP.				PURCHASE		REF. NO.		
1 8420000 CO 82		CO 823447	804		413080					
SHIP	SHIP NO.		l		l	SHIP DATE		SHIP WEIGHT		
	0					10/03/22		.000 EA		
LINE NO.	ITEM NO. / DESCRIPTION			U/M		QUANTITY / PRICE		AMOUNT		
	DATE IN	ence order number 12-5-22 T 12-8-22 37,104	823447							
01	46150 LABOR CU	JSTOMER ITEM COMME	NTS	HR	*3	1.000			00	
	QUOTE 12 C/S TO S CUSTOM A DASH A/C THAT									
	MB-CUSTO	OM AIR INSPECTED. HAT THE SYSTEM IS REALLY WELL. NO								
02	46150 LABOR CU	JSTOMER ITEM COMME	NTS	HR		3.500 150.000		525.	00	
		24389,127529 DIAGNOSE ISSUES IDEOUTS.								

NET SALES MISC. CHARGES **FREIGHT TAXES**

MISC. CHARGES 2 MISC. CHARGES 3

AMOUNT DUE



355 N DELAWARE ST PO BOX 30 (574) 773-7791 FAX (574) 773-7798

NAPPANEE IN 46550-0030

12/09/22

WARD-413080-RW21

6505 SHRESBURY LANE DUBUQUE IA 52003

USA

SHIP TO:

SOLD TO:

MIKE@WARDFARM.ORG

734-272-1434

MIKE WARD 12-5-22

413080 2017 VTDP 3412

4UZACHDT9HCJG9420

DOP 2-10-17 NAPPANEE IN 46550

USA

PACKING SLIP

PAGE

DATE: 12/08/22

DUE ON: 12/08/22

EXPORT:

N

TERMS:

Return part accompanied by this FORM must be returned to Newmar within 90 days of original receipt of the part and in accordance with the Newmar Parts Ordering Guidelines.

CUSTOMER		ORDER NO.	ORDER NO. SLS RE			PURCHASE		REF. NO.	
1 8420000		CO 823447	804		413	413080			
SHIP NO.			SHIP DATE		SHIP WEIGHT				
,	0					10/03/22		.000	EA
LINE NO.	ITEM NO. / DESCRIPTION			U/M		QUANTITY / PRICE		AMOUNT	
	MB-INST WARDROT FOUND TO BAD ANT REPLACT SLIDE OF MOVED TO ORDER TO CUT OLI AND REI WELDED TOGETHI COACH TO POSITIO COMPONI MOTOR.	rence order number PECTING THE BE SLIDE OUT. WE THAT THE MOTOR IS D NEEDS TO BE ED. THE KITCHEN DUT ISSUE HAS BEEN TO GOODWILL WORK \$440713, JOB #6. D MOTOR SHAFT OUT MOVED OLD MOTOR. COUPLER AND SHAFT ER. MOUNTED IN ALONG WITH MOTOR. DNED AND TIGHTENED ENTS. WIRED UP THE TESTED. THE SLIDE RUNNING SMOOTHLY	823447						
02	118883 PSO GEA	AR MOTOR "G"2.0RPM	W/BRK	EA		1.000 577.398		577.	40
02	21835 PSO BUS	SHING TRANTORQUE 3/	4 "	EA		1.000 63.166		63.	17

NET SALES MISC. CHARGES **FREIGHT TAXES**

MISC. CHARGES 2 MISC. CHARGES 3

AMOUNT DUE



355 N DELAWARE ST PO BOX 30 NAPPANEE IN 46550-0030 (574) 773-7791 FAX (574) 773-7798

SLS REP.

12/09/22

WARD-413080-RW21

6505 SHRESBURY LANE DUBUQUE IA 52003

USA

MIKE@WARDFARM.ORG

734-272-1434

EXPORT:

N

TERMS:

PURCHASE ORDER NO.

SOLD TO:

SHIP TO:

MIKE WARD 12-5-22 413080 2017 VTDP 3412

ORDER NO.

DOP 2-10-17

NAPPANEE IN 46550

4UZACHDT9HCJG9420

USA

CUSTOMER

Return part accompanied by this FORM must be returned to Newmar within 90 days of original receipt of the part and in accordance with the Newmar Parts Ordering Guidelines.

PACKING SLIP

DATE: 12/08/22

DUE ON: 12/08/22

PAGE

REF. NO.

1	8420000	CO 823447	804	413	080				
SHIP NO.					SHIP DATE		SHIP WEIGHT		
	0				10/03/22		.000 EA		
LINE NO.		ITEM NO. / DESCRIPTION	U/N	И	QUANTITY / PR	ICE	AMOUN	IT	
02	28452	rence order number AFT 3/4"X12" KEYED	823447 EA		1.000 34.424		34.42		
02	21832 PSO ADA	APTER 3/4" TO 3/4"	TTB1		1.000	16.70			
03	1310937 ACCENT	A RH ABOVE HEADLIGHT	EA EA		1.000 25.332		25.33		
03	05455 MISC PA	ARTS, SHOP SUPPLIES	EA ETC		1.000	2 m	10.00		
03	46150 LABOR (CUSTOMER ITEM COMME	HR		.500 150.000		75.00		
	ACCENT HEADLIC MB-REMC AND CLE 3M PRIN	REPLACE CHROME ABOVE DRIVER SHT. OVED ACCENT CHROME EANED. PREPPED WITH MER. FORMED AND LED NEW PIECE							
	CLIENT	OWNERS SIGNATURE							

NET SALES MISC. CHARGES FREIGHT TAXES MISC. CHARGES 2 MISC. CHARGES 3

AMOUNT DUE



355 N DELAWARE ST PO BOX 30 NAPPANEE IN 46550-0030 (574) 773-7791 FAX (574) 773-7798

12/09/22

6505 SHRESBURY LANE DUBUQUE IA 52003

USA

MIKE@WARDFARM.ORG

734-272-1434

EXPORT:

N

SOLD TO:

SHIP TO:

MIKE WARD 12-5-22 413080 2017 VTDP 3412 4UZACHDT9HCJG9420

DOP 2-10-17

NAPPANEE IN 46550

USA

TERMS:

Return part accompanied by this FORM must be returned to Newmar within 90 days of original receipt of the part and in accordance with the Newmar Parts Ordering Guidelines.

PACKING SLIP

DATE: 12/08/22

DUE ON: 12/08/22

PAGE

CUSTOMER		ORDER NO.	ORDER NO. SLS RE			PURCHASE		REF. NO.	
1 8420000		CO 823447	804		413	.3080			
SHIP	NO.		I			SHIP DATE		SHIP WEIGHT	
	0					10/03/22		.000	EA
LINE NO.		ITEM NO. / DESCRIPTION		U/M		QUANTITY / PF	RICE		AMOUNT
	I CONFI OF THE IT AS E	rence order number IRM THE PERFORMANCE ABOVE WORK&ACCEPT BEING SATISFACTORY A STATE SALES TAX						50.	
	-		3						

NET SALES MISC. CHARGES 1,327.02

.00

.00

FREIGHT TAXES 50.89 MISC. CHARGES 2 MISC. CHARGES 3 .00

.00

AMOUNT DUE

1,377.91

Coach#:413080

Owner
WARD MIKE
6505 SHREWSBURY LANE

DUBUQUE

Ā

52003

NEWMAR CORPORATION

CUSTOMER
Date Printed: 12/08/22

COPY

Warranty Repair Order: 440713

NEWMAR SERVICE - BLD

NAPPANEE

Warranty Status: OUT OF WARRANTY

Mileage: 00037104

Purchase Date:

2/10/2017

Email: MIKE@WARDFAM.COM Home Phone: 734-272-1434 Cell Phone: 734-395-6711

Job# 1 Job Start Date: 12/05/2022
Customer Complaint:
COMMENT ENTERED ON 12/28/2021
1B) WRITE UP AND CHECK OUT AT 6:55:54 AM BY CTITUS Job End Date: 12/08/2022

Dealer Correction:

COMMENT ENTERED ON 02/01/2022 AT 11:41:06 AM BY DBERRY

N Job Start Date: 12/08/2022 Job End Date: 12/08/20 Customer Complaint: COMMENT ENTERED ON 12/28/2021 AT 6:56:45 AM BY CTITUS 1B) CLEAN AFTER SERVICE REPAIRS Dealer Correction: COMMENT ENTERED ON 02/01/2022 AT 11:41:21 Job End Date: 12/08/2022 AM BY DBERRY

ω Job Start Date: 2/01/2022

Customer Complaint:
COMMENT ENTERED ON 12/28/2021 AT 6:57:51 AM BY CTITUS

KIDDE - FIRE EXTINGUISHER RECALL 2/01/2022

COMMENT ENTERED ON 02/01/2022 AT 11:41:49 AM BY DBERRY MB-CURRENT FIRE EXTINGUISHER DOES NOT FALL WITHIN THE RECALL

4

Job Start Date:
Customer Complaint:
COMMENT ENTERED ON 12/28/2021 AT 6:58:57 AM BY CTITUS
FREIGHTLINER - CIRCUIT BOARD DAMAGE AFFECTING LIGHTING FUNCTIONS Dealer Correction:

S

Job Start Date:
Customer Complaint:
COMMENT ENTERED ON 12/28/2021 AT 7:00:07 AM BY CTITUS
FREIGHTLINER - BRAKE LIGHTS NOT WORKING CORRECTLY Dealer Correction:

BLDG

11

H 46550

Coach#:413080

NEWMAR CORPORATION

Warranty Repair Order: 440713

Home Phone: 734-272-1434 Cell Phone: 734-395-6711 Email: MIKE@WARDFAM.COM 6505 SHREWSBURY LANE PUBUQUE IA

MIKE

52003

NAPPANEE

NEWMAR SERVICE

Service Performed By NEWMAR SERVICE - BLDG

46550

H

Job#

g

Mileage: 00037104 Warranty Status:

Purchase Date:

2/10/2017

OUT OF WARRANTY

Job Start Date: 12/06/2022 Customer Complaint:

Job End Date: 12/08/2022

COMMENT ENTERED ON 12/06/2022 AT 1:27:21 PM BY DBERRY 2B-CUSTOMER STATES-KITCHEN SLIDE OUT RUBBING AGAINST FLOOR BELOW REFER

Dealer Correction:

COMMENT ENTERED ON 12/06/2022 AT 1:27:21 PM BY DBERRY

MB-JF-ED-RAN THE ROOM IN. FOUND THAT THE SLIDE OUT FLOOR WAS RUBBING ON THE EDGE,
RIGHT BELOW THE REFER, WHICH COULD BE CAUSING THE SLIDE OUT AMD OUT. ADDED SHIMS ON
THE TWO REAR ROLLERS AND TRIED, BUT THE ROOM WAS TOO TIGHT AND WAS GETTING HUNG UP ON
THE TOP REMOVED THE SHIMS AND REMOVED THE REFER. MADE NEW MOUNTING BRACKETS FOR THE
BOTTOM OF THE REFER BECAUSE THE EXISTING ONE WERE BENT AND ALLOWING THE WEIGHT OF THE
REFER TO PUSH DOWN ON THE LEADING EDGE OF THE SLIDE OUT. NEW BRACKETS ARE MUCH
HEAVIER, 1/4" STEEL STRAP. WE INSTALLED THEM AND TESTED. THE SLIDE OUT IS OPERATING
WITHOUT HANG UP. ADJUSTED THE SLIDE OUT SO IT WOULD NOT EXTEND SO FAR. RECONNECTED
THE REFER. SECURED THE SLIDE OUT SO IT WOULD NOT EXTEND SO FAR. RECONNECTED
THE REFER AND SECURED THE TOP INTO PLACE. CUT A NEW TRIM PIECE FOR THE TOP. RAN SLIDE OUT
SEVERAL TIMES TO TEST, WITH NO ISSUES. SECURED THE CARPET BACK DOWN. POLISHED THE
REFER AND SECURED THE TOP INTO PLACE
COMMENT ENTERED ON 12/08/2022 AT 6:23:15 AM BY DBERRY
WE HAD TO TURN THE FREEZER WATER LINE OFF WHEN WE TOOK THE REFER OUT. THE PLASTIC
LINE BENT, POTENTIALLY COMPROMISING THAT PORTION OF THE LINE. REMOVED THE FITTING
BELOW THE VALVE. CUT THE BENT PORTION OUT AND REATTACHED THE LINE WITH A NEW FEMALE
FUND WATER TAND BELFY OFF TIMES.

WATER TESTED AND BLEW OUT LINES

Job Start Date: 12/08/2022 Job End Date: 12/08/2022
Customer Complaint:
COMMENT ENTERED ON 12/08/2022 AT 6:28:19 AM BY DBERRY
TECH STATES-C-STROM SLIDE OUT MODULES ARE AMPING OUT TOO HIGH, POTENTIALLY CAUSING
THE SLIDE OUT MOTOR TO BECOME DAMAGED

Dealer Correction:
COMMENT ENTERED ON 12/08/2022 AT 6:28:19 AM BY DBERRY
MB-JF-REPLACED WARDROBE SLIDE OUT, BEDROOM SLIDE OUT AND LIVING ROOM SLIDE OUT
CONTROL MODULES WITH KMB CONTROLLER. PROGRAMMED EACH CONTROLLER AND TESTED. GO

2

Date Printed: 12/08/22

Owner
WARD MIKE
6505 SHREWSBURY LANE
DUBUQUE
Home Phone: 734-272-1434
Cell Phone: 734-395-6711
Email: MIKE@WARDFAM.COM
Purchase Date: 2/10/2017 Customer Signature: Job# If you have a problem with the service work performed under the Newmar Expressed Warranty you must notify the Newmar Customer Service Department within seven (7) calendar days so that Newmar can assist you. I confirm the performance of the above work and accept it as being satisfactory. Newmar Repair Order: 440713 DBERRY@NEWMARCORP.COM Warranty Status: Mileage: 00037104 2/10/2017 : OUT OF WARRANTY Description IA 52003 Coach#:413080 Warranty Repair Order: 440713 NEWMAR CORPORATION Date: NAPPANEE Service Performed By NEWMAR SERVICE - BLDG 11 H 46550 Date Printed: 12/08/22