



ELLIS & WATTS INTERNATIONAL, INC
4400 GLEN WILLOW LAKE LANE BATAVIA, OH 45103
(513) 752-9000

6/25/01 SB-006

SERVICE BULLETIN

Start-up Issues

The purpose of this bulletin is to address an important service issue:

Important

It has become necessary for the Service Provider to perform many tasks during the course of our recent Start-up visits, that do not fall within the scope of work that we arranged with GE. I applaud all those involved for taking the initiative to work with GE in completing the tasks necessary to get our equipment up and running.

The purpose of this bulletin is to advise all service providers that you need to make sure to have detailed reports of the work that is not within the scope of work outlined in the INSTALLATION RESPONSIBILITY MATRIX found on page 1-3 of Technical Publication 468 Rev 0. This detailed report needs to be provided to us so there can be some capturing of the excess costs. Also it is very important that a GE representative sign the service report or report document that has the out of scope work listed on it. If there is any resistance to getting a signature please contact Ellis and Watts Service Department so we can work with you to resolve the problem. If there is no GE representative available to sign the report, please get the general contractor or a representative to sign the report and print his title.