

REVISION HISTORY

REV	DATE	PRIMARY REASON FOR CHANGE
Prelim A	Mar. 21, 2001 . . .	Initial Development Preliminary version. Information subject to change without notice
Rev 0	June 28, 2001 . . .	Initial Product Release
Rev 1	May 21, 2002 . . .	Added Signa TwinSpeed with EXCITE Technology system information throughout the document. Other major changes listed by section include the following Sec 1: Update power product offerings to E catalogs. Sec 2: Update TSCC & TGWC for revised E&W information; Added NEC 2002 Article references for MDP information; Added Network connection and telephone lines option to system connectivity requirements; Updated installed weight of Magnet, Enclosure, Body Coil, & Cryogenics; Updated TAC Cabinet dimensions drawing. Sec 4: Added Outdoor TSCC & TGWC Operating Environment temperature & humidity specifications; Updated Water Cooled TSCC water cooling requirements; Clarified Magnet Room exhaust fan intake location requirement. Sec 5: Revised Voltage Transient specification; Updated Facility Ground Wire measurement techniques; Added NEC 2002 Article references. Sec 6: Updated miscellaneous system interconnects. Sec 7: Added illustration of Magnet Minimum Ceiling height area requirement; Clarified RF Shield Room vendor responsibility to supply torque specifications for all anchors, studs, and fastening hardware to meet the clamping force specified. Sec 8: Update magnet moving dimensions height. Sec 9: Updated references to Network connection and telephone lines option to system connectivity; Updated Cryogenic Vent connected to magnet prior to magnet ramp-up. Sec 10: Added new & deleted obsolete test equipment & part numbers. Appendix C: Added Ellis & Watts "Prerequisites for Scheduled Performance Verification of Chillers For Signa TwinSpeed" document.
Rev 2	Nov. 19, 2002 . . .	Direction 2128126 updated to Rev 1. Changed SRF Cabinet to 1.5T SRFD II Cabinet information throughout the manual. Sec 1: Added M1090ZP & M1090ZN OW ONLY Long Cables; System Cooling & MDP selections Water Cooled TGWC added MDP turnkey solution choice to flowchart illustration; Added UPS for Magnet Monitor to Mobile magnet catalogs; For TSCC catalogs table added note for MDP required; Facility Options added full system UPS and Bypass panel options catalogs. Sec 2: Added Multiple MR System Sites shared Equipment Room requirements; Cradle extensions information added for TRM Coil replacement; Mounting requirements clarified for MDP top breaker highest position; Added UPS for Magnet Monitor to Mobile magnet catalogs; Revised System Monitoring & Support Connectivity Requirements for Magnet Monitor; Updated ACGD/PDU Cabinet weight & center of gravity values. Sec 3: Corrected reference typographical error; Magnetic Isogauss line plots added 40mT & 200mT required by IEC 60601 – 2 – 33 6.8.3 bb. Sec 4: Revised hearing protection requirement in the Magnet Room; Clarified water cooling required 365 days per year for Water Cooled TSCC & Water Cooled TGWC; Added metric value for recommend Magnet Room ventilation; Exhaust Fan illustrations added Room Ventilation Requirements/Recommendations reference; Added roof hatch delivery situation to Cryogenic Vent inspection CAUTION; Typical Cryogenic Vent Detail added height requirement for RF Shielded Room Contractor supplied vent pipe/waveguide in Magnet Room. Sec 5: Protective Disconnect Set-Up clarified power recommendation for Shield Cooler & TSCC; Added PDU feeder wiring requirement with full system UPS option; Updated Common Ground Stud location dimension in Magnet Room Grounding Requirements illustration. Sec 6: Added notes to identified RF Transmit & RF Receive cables; Updated miscellaneous system interconnects; Cable Groups 8 & 12 revised for Gradient Cable length reduction. Sec 7: References typo error corrected; Added use of Megger Insulation Tester to Electrical Isolation Measurement Method for Anchor Hardware Requirements for MR Equipment Inside RF Shielded Room. Sec 8: Added Transportation Environmental Conditions. Sec 10: Added Resistance Meter to table of Rigger/Customer Supplied Equipment. Appendix D: Added REQUIREMENTS FOR EQUIPMENT ROOM SHARED BY MULTIPLE MR SYSTEMS.
Rev 3	May 1, 2003 . . .	Added BrainWave Option For Signa 1.5T TwinSpeed with EXCITE Technology systems ONLY, information includes new revised heat output values. Sec 1: Table 1–11 Note 2 changed M3043TA to M3043TC; Deleted Remote Keyboard Option for use with Operator Workspace PC LCD catalogs. Sec 2: Illustration 2–33 corrected Magnet Monitor vertical box and mounting flange dimensions. Sec 4: Table 4–2 bold Note 2 to emphasize air cooling load average for maximum value; Section 4–4–4 Shield/Cryo Cooler Compressor Water Cooling Requirements For Sites With TGWC Table 4–7 Note 6 added Ethylene Glycol or Propylene Glycol wording. Section 4–4–5 Water Cooled TGWC Requirements Table 4–8 updated Pressure Drop values, added note clarifying value for water and factor for 50/50, and Illustration 4–4 Water Flowrate/Temperature requirement. Section 4–7–3 Design Guidelines for acoustics added Structural Vibration Control information. Section 4–8 Room Ventilation pressure equalization waveguide requirement added IEC regulation reference. Section 4–14–4 Transient Vibration specification added clarifications for measurements. Sec 5: Section 5–3–1 MDP and Illustration 5–1 clarified Emergency Off buttons provided with GE MDP option; Illustration 5–1 added SPLICE on Run 296 BLK wire connection & clarified Emergency OFF. Illustration 5–3 external conduit metal requirement added 2002 NEC reference, also updated RF Filter metallic conduit requirement and filter location for 2002 NEC requirement. Sec 6: Illustration 6–1 added Equipment Room and Control Area delineating lines (requested by Installation Specialist); Illustration 6–1, Tables 6–2 & 6–3 corrected cable Group 81 to connect between E02 and PP1Group 25 added missing Run 726; Table 6–3 (multiple pages) added M3044TC to notes for increased usable length; RF Transmit interconnects changed for new material & standard length cut at site. Added Group 72 from MR1 to MG2 for with RF Transmits (removed from Groups 25 & 45). Sec 9: Changed hospital to facility in several items. Sec 10: Deleted RF survey apparatus no longer available from GE Medical Systems.

REVISION HISTORY (Continued)

PAGE	REV	PAGE	REV	PAGE	REV	PAGE	REV	PAGE	REV
Title Page	3	2-10 to 2-12	1	5-6 to 5-7	1	6-44 to 6-45	3	9-3	3
GE Logo	—	2-13	2	5-8	0			9-4	1
Direction 2128126	*	2-14	1	5-9	1	RF SHIELDED ROOM		9-5	0
A to B	3	2-15	2	5-10	3	Tab MR257	—	9-6	1
i to ii	3	2-16 to 2-19	1	5-11	1	7-1	1	9-7	3
iii	1	2-20 to 2-21	2	5-12	3	7-2 to 7-4	0	9-8	1
vi	2	2-22 to 2-75	3	5-13	2	7-5	1		
v	3			5-14 to 5-15	1	7-6 to 7-12	0	TOOLS & TEST	
vi	2	MAGNETIC FIELD		5-16	3	7-13 to 7-14	2	EQUIPMENT	
vii to viii	0	CONSID.		5-17	2	7-15	0	Tab MR260	—
ix	1	Tab MR253	—	5-18	1	7-16	2	10-1	3
		3-1	0			7-17 to 7-19	0	10-2	blank
SYSTEM CONFIG.		3-2	blank	INTERCONNECT DATA		7-20	2	10-3 to 10-4	3
Tab MR251	—	3-3 to 3-4	0	Tab MR256	—	7-21 to 7-25	0	10-5	0
1-1	1	3-5 to 3-7	2	6-1	3	7-26	2	10-6 to 10-10	3
1-2	blank			6-2	blank	7-27 to 7-30	1		
1-3 to 1-8	2	SITE ENVIRONMENT		6-3 to 6-5	3	SHIPPING &		A	
1-9	3	Tab MR254	—	6-6	0	DELIVERY		Tab MR301	—
1-10 to 1-11	2	4-1 to 4-2	3	6-7	2	Tab MR258	—	A-1 to A-7	0
1-12 to 1-13	1	4-3	1	6-8 to 6-9	3	8-1	0		
1-14	3	4-4	0	6-10	1	8-2	blank	B	
1-15	2	4-5 to 4-43	3	6-11	2	8-3 to 8-4	2	Tab MR302	—
1-16	1			6-12	3	8-5	3	B-1 to B-4	0
		POWER		6-13	1	8-6	2		
ROOM LAYOUTS		REQUIREMENTS		6-14 to 6-15	3	8-7	1	C	
Tab MR252	—	Tab MR255	—	6-16	1			Tab MR303	—
2-1 to 2-2	3	5-1	1	6-17 to 6-24	3	PREINSTALL.		E&W schedule 02/14/02*	
2-3	0	5-2	blank	6-25 to 6-40	1	CHECKLIST			
2-4	3	5-3	0	6-41	2	Tab MR259	—	D	
2-5	1	5-4	1	6-42	1	9-1	0	Tab MR304	—
2-6 to 2-9	2	5-5	0	6-43	2	9-2	blank	D-1 to D-4	2

* This revision number/letter corresponds to the indicated document's revision control system.