

FCT SERVICE NOTE

SN05081109a

Class A Service information enclosed.

Date: August 11, 2005

Subject: VCT Option 5 Ethernet Connections

Effectivity: VCT M3 with HP XW8200 HOST

Details: NOTE: This Service Note Describes how to connect up the Ethernet Cables to the HPXW8200 before M3a SW is deployed. Once M3a SW is deployed this procedure is not required.

If you receive an HP8200 computer you before M3 SW is deployed than you Must follow this procedure.

OPTION 5 Ethernet Connections

Feature Summary

The basic difference between the XW8000 and XW8200 is that the PCI-bus is initiated from opposite ends. Looking at the back of the computer as it lays on its side in the rack, the ethernet ports would initialize differently as shown here: (basically, the two cards are reversed)

Rather than change any labels on the computer and risk confusion in the field, it was decided to correct this in software. For now, installations must simply reverse connections (A <--> C) and (B <--> D). At Pathfinder M3 and VCT M3A the labels will again be the same between the XW8000 and the XW8200.

HP Port	M3 8000 Cable	M3 8200 Cable	M3A Both Cable
A	A	C	A
B	B	D	B
C	C	A	C
D	D	B	D

The cable labels will not change for VCT systems that contain an HP xw8200 (and M3 Software).

- ☐ Cable label A will connect to HP8200 port C
- ☐ Cable label C will connect to HP8200 port A

- ☐ Cable label B will connect to HP8200 port D
- ☐ Cable label D will connect to HP8200 port B

When the M3A Software is loaded on these specific systems the cables back are required to be placed back into to their original respective ports as they are currently on the HP 8000 we use for VCT today.

Resolution: N/A

James Lehouillier
Console Service Methods Design Engineer